# Oil Field Environmental Incident Summary

Responsible Party:ENERGYQUEST II, LLCWell Operator:ENERGYQUEST II, LLCWell Name:JOHN WADDLE1-29

Field Name: STARBUCK

**Well File #:** 8452

Facility ID #:

County: BOTTINEAU
Twp Rng Sec Qtr: 161 78 29

**Location Description:** 

**Submitted By:** Larry Davis

Received By:

Contact Info: Larry Davis

4526 RESEARCH FOREST DR

SUITE 200

THE WOODLANDS TX 77381

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: 0.5 Mile

Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained: Yes - On Facility Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

**Brine** 50 Barrels 48 Barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd:

Risk Evaluation:

No immediate risk as the release was contained within the berm.

Areal Extent:

#### Potential Env. Impacts:

No impact outside of the facility; release was completely contained within berm. Water was vacuumed up and returned to the tank.

### Action Taken/Planned:

Upon discovery, the switch was reset, and the pump then shut off as it should. A vacuum truck was called out to recover released water. Recovered water was returned to the tank for injection. The Murphy switch was cleaned and returned to service, but an electrician is on the site today to identify and correct any additional problems related to the switch failure.

#### Wastes Disposal Location:

Recovered water was returned to produced water tank on location. No additional wastes removed.

Other Agencies Involved:

## **Updates**

Date: 3/16/2017 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Martin, Russell

Notes:

Release, due to tank overflow, remained on location according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update