

Oil Field Environmental Incident Summary

Incident: 20170526114539 **Notice:** 5/26/2017 11:45 **Occurred:** 5/24/2017 16:30

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS CORPORATION

Well Name: Hawkeye Station Tanks

Field Name: HAWKEYE

Well File #:

Facility ID #: 550014-02

County: MCKENZIE

Twp Rng Sec Qtr: 153 95 26

Location Description:

Submitted By: Alex Beach

Received By:

Contact Info: Troy Brunsell
3015 16TH ST SW STE 20
MINOT ND 58701

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 200 Feet

Nearest Water Well: 200 Feet

Type of Incident: Fire

Release Contained: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other						

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 6/1/2017

Written Report Recd: 6/8/2017

Risk Evaluation:

The incident caused a small fire.

Areal Extent:

Potential Env. Impacts:

There was no potential for environmental impacts.

Action Taken/Planned:

The operator isolated the stainless braided hose. The person assigned as Fire Watch extinguished the fire.

Wastes Disposal Location:

All recovered wastes will be transported to an approved waste disposal facility.

Other Agencies Involved:

Updates

Date: 5/30/2017 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: DeVries, Taylor

Notes:

According to the spill report, a fire occurred on the well pad. Further follow-up is needed to ensure no contaminants were released off the well pad.

Updated Volumes and Contaminant None at the time of this update

Date: 6/29/2017 **Status:** Inspection

No Further Action:

Author: Martin, Russell

Notes:

6/28/2017 at 16:00, on location. Site is not a wellpad, it is at the Hawkeye Compressor Station. Called report contact to determine location of fire due to large size of facility. Report contact says fire occurred inside one of the buildings when a piece of welding slag fell on a metal instrumentation hose, burning a hole in the hose and causing it to catch fire. Due to the fact that the fire was contained and put out within the building, and the only material affected was the instrumentation hose, no inspection is needed. No further follow-up required at this time. No photos taken.

Updated Volumes and Contaminant None at the time of this update