

Oil Field Environmental Incident Summary

Incident: 20170919113806 **Notice:** 9/19/2017 11:38 **Occurred:** 9/18/2017 12:00

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: HOLDREDGE 43-33 SWD

Field Name: EAST FORK

Well File #: 12144

Facility ID #:

County: WILLIAMS

Twp Rng Sec Qtr: 156 99 33

Location Description:

Submitted By: Cooper Fink

Received By:

Contact Info:
Cooper Fink
PO BOX 268870
OKLAHOMA CITY OK 73126

Affected Medium: Topsoil

General Land Use: Cultivated

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Other

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels	1	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 10/16/2017

Written Report Recd: 10/19/2017

Risk Evaluation:

None

Areal Extent:

100' long x 20' wide area off location

Potential Env. Impacts:

Topsoil

Action Taken/Planned:

Hydro-Vac cleaned contaminated gravel on location and grader will scrap up the contaminated area off location.

Wastes Disposal Location:

TBD

Other Agencies Involved:

NDIC - Jessica Gilkey @ 4:00 PM 9/18/2017

NDDoH @ 4:30 PM 9/18/2017

Updates

Date: 9/19/2017 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Martin, Russell

Notes:

Release due to unspecified cause, was not contained on location according to the report. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 9/25/2017 **Status:** Inspection **No Further Action:**

Author: Schiermeister, Robin

Notes:

Arrived at the salt water disposal pad at 12:24 on 9-21-2017. It was cloudy and raining.

One barrel of a water and oil mixture went off location southwest of the pad. The contaminated area spanned 20 by 100 feet. The contamination mostly consisted of water according to the operator on site which was scraped up and disposed of. During the inspection, no odors or other contamination were noted. An inspection is needed in the spring of next year to check for revegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 9/5/2018 **Status:** Inspection **No Further Action:**

Author: Torgerson, Brad

Notes:

On 9/5/2018 at 12:15 pm - Sunny and 54 Degrees F - I visited the Continental Resources Catwalk SWD facility and the Continental Resources - Holdridge 43-33 SWD Injection well location. Gully-like erosion areas were noted protruding from the SW and SE areas of the Catwalk facility. Lots of weeds were noticed east and southeast of the 43-33 SWD injection well location.

Updated Volumes and Contaminant None at the time of this update

Date: 9/6/2019 **Status:** Awaiting Documentation **No Further Action:**

Author: Suess, Bill

Notes:

The RP has been contacted to request verification of remediation at the site. Once the documents are reviewed the site will be revisited to assure proper revegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 1/2/2020 **Status:** Correspondence - Vegetation Check **No Further Action:**

Author: Suess, Bill

Notes:

Received follow-up report from the RP. Vegetation check needed in Spring 2020.

Updated Volumes and Contaminant None at the time of this update

Date: 7/23/2020

Status: Inspection - No Action Required

No Further Action:

Author: Sues, Bill

Notes:

Inspected the site on 7/21/2020. No adverse environmental impacts associated with this incident were observed. The vegetation appeared healthy and consistent with the surrounding area. No further action is warranted.

Updated Volumes and Contaminant None at the time of this update