

# *Oil Field Environmental Incident Summary*

**Incident:** 20180130090250      **Notice:** 1/30/2018    09:02      **Occurred:** 1/29/2018    09:36

**Responsible Party:** SCOUT ENERGY MANAGEMENT LLC  
**Well Operator:** SCOUT ENERGY MANAGEMENT LLC  
**Well Name:** DICKINSON-HEATH-SAND UNIT 25  
**Field Name:** DICKINSON  
**Well File #:** 4293  
**Facility ID #:**  
**County:** STARK  
**Twp Rng Sec Qtr:** 140 97 26 SE SE  
**Location Description:** Spill occurred on location but ran off location through a hole in the berm  
**Submitted By:** REBECCA Sample  
**Received By:**

**Contact Info:** rebecca Sample  
 4901 LBJ FREEWAY, STE 300  
 DALLAS TX 75244

**Affected Medium:** Topsoil  
**General Land Use:** Pasture  
**Near. Occupied Bldg:** 400 Feet  
**Nearest Water Well:** 400 Feet  
**Type of Incident:** Pipeline Leak  
**Release Contained:** No  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	2	Barrels	2	Barrels	2	barrels
<b>Other</b>						

**Oth Rel. Contaminant:** N/A

**Date Inspected:**

**Clean Up Concluded:** 7/29/2018

**Written Report Recd:** 12/7/2018

**Risk Evaluation:**

There is a stock pond at the bottom of the hill.

**Areal Extent:**

30 feet x 1 foot. one spot 10 feet wide

**Potential Env. Impacts:**

There may be some grass that will be impacted

**Action Taken/Planned:**

A dike was built to contain any more run-off, although there should not be as the well was shut in. Contaminated soil will be removed and replaced to prevent any further contamination.

**Wastes Disposal Location:**

R360 Chimney Butte facility

**Other Agencies Involved:**

## Updates

---

**Date:** 1/30/2018      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** Schiermeister, Robin

**Notes:**

Release, due to a pipeline leak, did not remain on site. An inspection will be needed to determine the extent of damages.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 1/30/2018      **Status:** Inspection      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

On location 1/30/2018, at 2:58pm. Release off location to the West. There is a dirt berm to the west. Impacts are seen inside off-pad berm but it is difficult to determine impacts outside of berm. Further follow-up is required.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 2/8/2018      **Status:** Inspection      **No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

Arrived on location at 15:25. 6 degrees F, northeast wind 10-20 mph, snowing. Observed the site and took photos. It appeared that new soil had been added and graded to an area west of the well pad in an area approximately 100 feet by 100 feet. Further follow-up needed.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 8/29/2018      **Status:** Inspection      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

8/22/2018 at 10:39, on location. Wellpad berm has been rebuilt, and temporary berm constructed for incident has been removed. Area involved in incident appears to have been remediated and vegetation is growing, and shows evidence of being well grazed by cattle. However site has had numerous other spills going back to the 1970's, one spot near the apparent incident area shows elevated electrical conductivity readings. No further follow-up at this time for this particular incident.

**Updated Volumes and Contaminant**    None at the time of this update