

Oil Field Environmental Incident Summary

Incident: 20181105075955 **Notice:** 11/5/2018 07:59 **Occurred:** 11/4/2018 07:44

Responsible Party: SCOUT ENERGY MANAGEMENT LLC

Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: STRATTON C 3

Field Name: WILEY

Well File #: 2566

Facility ID #:

County: BOTTINEAU

Twp Rng Sec Qtr: 161 82 24 NE SW

Location Description:

Submitted By: REBECCA Sample

Received By:

Contact Info: Rebecca Sample
4901 LBJ FREEWAY, STE 300

DALLAS TX 75244

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 1 Mile

Nearest Water Well: 1 Mile

Type of Incident: Equipment Failure

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2000	Barrels	2000	Barrels	2000	barrels

Other

Oth Rel. Contaminant: N/A

Date Inspected:

Clean Up Concluded: 11/5/2018

Written Report Recd: 9/6/2019

Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Env. Impacts:

N/A

Action Taken/Planned:

Trucks were dispatched and recovered the water was returned to storage tanks for disposal.

Wastes Disposal Location:

R360 Chimney Butte

Other Agencies Involved:

Updates

Date: 11/5/2018 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report, the release of 2,000 barrels of brine was contained to the well pad. Due to the large quantity spilled a site inspection is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 11/8/2018 **Status:** Inspection **No Further Action:**

Author: O'Gorman, Brian

Notes:

Arrived at the location at 12:30. 14 degrees F, Northwest wind 10-15 mph, Partly Cloudy. Walked the perimeter of the well pad and took photos. Some excavation of soils on the well pad had occurred at the time of inspection. The staining on the berms surrounding the well pad was evident and it did not appear that a breach occurred above the diking. However, it appeared that some of the water may have saturated the berms/floor and moved beyond the footprint of the well pad. Another inspection should occur next growing season to collect field analysis from soils outside of the well pad. More follow-up needed. Photos added to the incident folder.

Updated Volumes and Contaminant None at the time of this update

Date: 9/12/2019 **Status:** Correspondence **No Further Action:**

Author: Suess, Bill

Notes:

This site needs to be re-inspected for verification of Remediation and Revegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 11/21/2019 **Status:** Inspection - No Action Required **No Further Action:**

Author: Martin, Russell

Notes:

11/7/2019 at 14:28, on location. Walked site, vegetation around site appears to have no recent issues, though a lack of vegetation is noted in field to south of facility, evident since at least 2006. No further follow-up at this time.

Updated Volumes and Contaminant None at the time of this update