

# Oil Field Environmental Incident Summary

**Incident:** 20190116114519      **Notice:** 1/16/2019      11:45      **Occurred:** 1/15/2019      16:00

**Responsible Party:** Denbury Onshore  
**Well Operator:** DENBURY ONSHORE, LLC  
**Well Name:** CANTER 33 WSW 15  
**Field Name:** CEDAR HILLS  
**Well File #:** 8119  
**Facility ID #:**  
**County:** BOWMAN  
**Twp Rng Sec Qtr:** 131 105 33 NW NW  
**Location Description:** Water source well  
**Submitted By:** Eric Hartzell  
**Received By:**  
**Contact Info:** Roy Madsen  
 5320 LEGACY DR  
 PLANO TX 75024-3127

**Affected Medium:** Topsoil  
**General Land Use:** Pasture  
**Near. Occupied Bldg:** 2 Mile  
**Nearest Water Well:** 2 Mile  
**Type of Incident:** Valve/Piping Connection Leak  
**Release Contained:** No  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	5	Barrels				

**Oth Rel. Contaminant:** Source water

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

No risk

**Areal Extent:**

4 bbls. of source water migrated off location to the southwest 145".

**Potential Env. Impacts:**

No surface water was affected.

**Action Taken/Planned:**

Transfer pump was shut down and locked out. Repair or replace.

**Wastes Disposal Location:**

N/A

**Other Agencies Involved:**

## Updates

---

**Date:** 1/16/2019      **Status:** Reviewed - Follow-up Required

**No Further Action:** ☒

**Author:** O'Gorman, Brian

**Notes:**

Release, due to a valve/piping connection leak, was not contained, according to the report. Further follow-up needed.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 1/16/2019      **Status:** Inspection

**No Further Action:** ☒

**Author:** DeVries, Taylor

**Notes:**

Inspection Date: 1/16/2019

Arrived on location at 1530. Inspected location and was unable to locate a water release as described. There was a vac truck on site removing water from a tank berm. Spoke with Denbury employee and they said the spill occurred from the tank berm where they were vacuuming. I did not notice any wet soil off of location. Location is surrounded by pasture land that has cattle and horses close by. Contact will be made with responsible party to make sure I was in the correct location.

Photos were taken and can be found in the report folder.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 1/25/2019      **Status:** Correspondence

**No Further Action:** ☒

**Author:** DeVries, Taylor

**Notes:**

Contact was made with responsible party. I was in the correct location. A photo of the release given by the RP is in the report folder. It shows the path of the formation water release. Follow-up is needed in summer 2019 to assess vegetation growth.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 6/12/2019      **Status:** Inspection

**No Further Action:** ☒

**Author:** Martin, Russell

**Notes:**

6/4/2019 at 15:51, on location. Area affected by spill recently tilled up along with nearby hay field. Follow-up end of summer or next year.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 6/24/2020

**Status:** Inspection - No Action Required

**No Further Action:** ☒

**Author:** Martin, Russell

**Notes:**

6/24/2020 at 14:31, on location. Tilled area noted in last year's inspection appears to have been cultivated this year, uniform planting rows visible. No bare spots noted. No further follow-up needed.

**Updated Volumes and Contaminant** None at the time of this update