

Oil Field Environmental Incident Summary

Incident: 20190511090154 **Notice:** 5/11/2019 09:01 **Occurred:** 5/10/2019 15:00

Responsible Party: NEWFIELD PRODUCTION COMPANY
Well Operator: NEWFIELD PRODUCTION COMPANY
Well Name: JORGENSON FEDERAL 148-96-10-15-1H
Field Name: LOST BRIDGE
Well File #: 31137
Facility ID #:
County: DUNN
Twp Rng Sec Qtr: 148 96 3 SW SW
Location Description:
Submitted By: Tim Eaton
Received By:
Contact Info: Tim Eaton
4 WATERWAY SQUARE PL, STE 100
THE WOODLANDS TX 77380

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Fire

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None, fire burned out

Areal Extent:

Along the north slope of the pad

Potential Env. Impacts:

None

Action Taken/Planned:

Crew attempted to extinguish the fire but it burned itself out. Hydro-vac with freshwater sprayed down the slope. Landowner brought fire truck to make sure it was out. Will not install so close to flares going forward.

Wastes Disposal Location:

NA, netting burnt up.

Other Agencies Involved:

Updates

Date: 5/13/2019 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: Stockdill, Scott

Notes:

According to the incident summary, this release burned a side of the pad. Follow-up is necessary to ensure no fluids were involved in the release and to confirm freshwater was used to extinguish the fire.

Updated Volumes and Contaminant None at the time of this update

Date: 6/3/2019 **Status:** Inspection

No Further Action:

Author: Schiermeister, Robin

Notes:

Arrived on site at 19:27 on 5-28-2019. The sun was setting and temperatures were in the 60s. The fire occurred north off the well pad on the hill that contained meshing for erosion control. During the inspection no signs of the fire could be seen. Called the responsible party who said the fire occurred just along the meshing on the north which instantly burned up. There is a lack of meshing north of the pad; however, no other signs of the fire or contamination. No further follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update