

# Oil Field Environmental Incident Summary

**Incident:** 20190514100903      **Notice:** 5/14/2019    10:09      **Occurred:** 5/13/2019    12:30

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC  
**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC  
**Well Name:** CAPA-MADISON UNIT G-206  
**Field Name:** CAPA  
**Well File #:** 1015  
**Facility ID #:**  
**County:** WILLIAMS  
**Twp Rng Sec Qtr:** 155 96 36 NE NW  
**Location Description:** Receiver located at approximately 48.208487,-102.966032  
**Submitted By:** Kathleen Kangas  
**Received By:**  
**Contact Info:** Kathleen Kangas  
 1501 MCKINNEY  
 HOUSTON TX 77010

**Affected Medium:** Topsoil  
**General Land Use:** Other - Described Above  
**Near. Occupied Bldg:** 0.9 Mile  
**Nearest Water Well:** 0.9 Mile  
**Type of Incident:** Valve/Piping Connection Leak  
**Release Contained:** No  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	0.2	Barrels			0.18	barrels
<b>Oth Rel. Contaminant:</b>	condensate					

**Date Inspected:**  
**Clean Up Concluded:** 5/22/2019  
**Written Report Recd:** 6/17/2019

**Risk Evaluation:**  
 no immediate risks identified at this time.

**Areal Extent:**  
 Approximately 20 ft X 100 ft

**Potential Env. Impacts:**  
 Topsoil is affected. No water impacts at this time.

**Action Taken/Planned:**  
 3rd party contractors have been notified, One Calls are being placed, and removal of affected soil is being coordinated.

**Wastes Disposal Location:**  
 At an approved waste disposal facility.

**Other Agencies Involved:**

## Updates

---

**Date:** 5/14/2019      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this spill impacted the surrounding area. Follow-up is necessary.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 5/21/2019      **Status:** Inspection      **No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

Arrived on location at 10:15. 55 degrees F, Cloudy, East wind 10-20 mph. Observed the site and took photos. At the time of inspection the contractor was leveling off the backfilled soil. Spoke with the company's environmental consultant who let me know that he had collected confirmation samples and would provide the report after the results were obtained. More follow-up needed. Photos added to the incident folder.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 6/1/2020      **Status:** Correspondence - More Follow-up Required      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

Contact will be made with responsible party for confirmation samples. Further follow-up is needed.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 10/5/2021      **Status:** Inspection - More Follow-up Required      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

Inspection Date: 10/5/2021

Arrived on location at 1240. Vegetation has mostly grown back within the old excavation area. There is still a bare patch of ground by the yellow well head in the bottom. As well as a few spots where the vegetation is very sparse in the bottom. Groundwater monitoring continues at this location. Photos were taken and can be found in the incident folder.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 7/20/2022      **Status:** Correspondence - No Action Required      **No Further Action:**

**Author:** Sues, Bill

**Notes:**

This incident occurred at the same location as GEIR #9287 and will be tracked under that incident number.

**Updated Volumes and Contaminant** None at the time of this update