

Oil Field Environmental Incident Summary

Incident: 20190806160755 **Notice:** 8/6/2019 16:07 **Occurred:** 8/6/2019 08:40

Responsible Party: SCOUT ENERGY MANAGEMENT LLC

Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: DURNIN A 2R

Field Name: WILEY

Well File #: 8509

Facility ID #:

County: BOTTINEAU

Twp Rng Sec Qtr: 161 81 30 NW NE

Location Description: A small area next to the location had some emulsion spill on to it.

Submitted By: Beki Sample

Received By:

Contact Info:
Beki Sample
4901 LBJ FREEWAY, STE 300
DALLAS TX 75244

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 0.5 Mile

Nearest Water Well: 0.5 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	7.5	Barrels	7.5	Barrels		
Brine	7.5	Barrels	7.5	Barrels		

Other

Oth Rel. Contaminant: N/A

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

N/A

Areal Extent:

20' x 20' A very small area received an amount of the spill

Potential Env. Impacts:

N/A

Action Taken/Planned:

Contaminated soil was dug up and removed from the well site and area where the emulsion left location. The valve was replaced

Wastes Disposal Location:

R360 facility

Other Agencies Involved:

Updates

Date: 8/6/2019 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Martin, Russell

Notes:

Release due to valve/piping connection leak, was not contained on location according to the report. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 8/7/2019 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Torgerson, Brad

Notes:

On 8/7/2019 at 2:30 PM - Sunny and 73 Degrees F - I visited the Scout Energy Management LLC - Durnin A 2R production site. It appeared that a leak occurred near the wellhead and ran to the NNW of the well head. No secondary containment around this production location. Two roll-off containers filled with soil and wheat were on location. Soil appeared to have been scraped up on the location and to the north of the location. Elevated soil conductivity readings were measured north of the facility anchoring system (deadmen). Additional excavation of salt impacted soils north of the location may be necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 8/14/2019 **Status:** Inspection **No Further Action:**

Author: DeVries, Taylor

Notes:

Inspection Date: 8/14/2019

Arrived on location 1200. There is a small pile of soil on the well pad location. The agricultural field surrounding the well pad has multiple dead spots to the north. Some of the spots have kosha growing. More follow-up will be needed with company on clean up and the dead spots.

Photos were taken and can be found in the report folder.

Updated Volumes and Contaminant None at the time of this update

Date: 3/6/2020 **Status:** Correspondence - More Follow-up Required **No Further Action:**

Author: Martin, Russell

Notes:

Conversation with responsible party on 8/16/2019. At that time RP had plans to perform some more work at the site, including spreading the small pile of soil on location as it is replacement soil for the site. Sampling planned to occur before the soil is spread.

Updated Volumes and Contaminant None at the time of this update