

# *Oil Field Environmental Incident Summary*

**Incident:** 20190808113143      **Notice:** 8/8/2019      11:31      **Occurred:** 8/8/2019      07:25

**Responsible Party:** SCOUT ENERGY MANAGEMENT LLC

**Well Operator:** SCOUT ENERGY MANAGEMENT LLC

**Well Name:** MHMU 12D

**Field Name:** MEDORA

**Well File #:** 4024

**Facility ID #:**

**County:** BILLINGS

**Twp Rng Sec Qtr:** 139 102 13 SE SW

**Location Description:**

**Submitted By:** Beki Sample

**Received By:**

**Contact Info:**  
Beki Sample  
4901 LBJ FREEWAY, STE 300  
DALLAS TX 75244

**Affected Medium:** Topsoil

**General Land Use:** Badlands Terrain

**Near. Occupied Bldg:** 0.8 Mile

**Nearest Water Well:** 0.8 Mile

**Type of Incident:** Pipeline Leak

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1	Gallons	1	Gallons	0	gallons
<b>Brine</b>	15	Barrels	15	Barrels	14	barrels

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 8/22/2019

**Written Report Recd:** 10/14/2019

**Risk Evaluation:**

There is no immediate risk to health

**Areal Extent:**

1' x 200'

**Potential Env. Impacts:**

There will be some potential vegetation kill. Vegetation consists of grass and sagebrush.

**Action Taken/Planned:**

Well was shut in. Berms were built to contain released product. One-Call was made. Vac truck was dispatched to recover the saltwater. Pipeline will be dug up and either replaced or repaired.

**Wastes Disposal Location:**

Indian Hills Disposal

**Other Agencies Involved:**

U.S. Forest Service

## Updates

---

**Date:** 8/8/2019      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

Release due to pipeline leak, was not contained on location according to the report. Follow-up is necessary.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 8/8/2019      **Status:** Inspection      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

On location 8/8/2019, at 12:31pm. Release surfaced on the north side of location. It flowed off location to the north then flowed towards the west and southwest. Impacts were to Forest Service lands. Company was instructed by the forest service to treat impacted area with Biocal. Further follow-up is required to check on vegetation growth.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 11/19/2020      **Status:** Inspection - No Action Required      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

11/18/2020 at 13:52, on location. Walked site, north/north east section of wellpad slope and lease road scraped and graded, work appears related to rebuilding the entrance. Drainage off the north side of the wellpad leading to the southwest is vegetated, no visible saltwater impact in the immediate area. However, further to the southwest, approximately 100 ft west of the pad, is a large, 50 ft x 25 ft bare spot with high electric conductivity, between 6 - 14 milliSiemens (mS), (background readings including north of the pad where the spill occurred range between 0.5 - 3 mS), indicate possible historic contamination. No further follow-up needed at this time.

**Updated Volumes and Contaminant**    None at the time of this update