



## **Updates**

---

**Date:** 8/6/2020      **Status:** Reviewed - Follow-up Required

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, there was a release of condensates that was not contained. Further follow-up is needed.

**Updated Volume:** None at the time of this update

---

**Date:** 9/9/2020      **Status:** Inspection - No Action Required

**Author:** Martin, Russell

**Notes:**

9/3/2020 at 11:47, on location. Areas involved appear to have been disturbed due to installation of a pipeline. Besides the lack of vegetation within the pipeline scar, no other issues noted. Further follow-up dependent on pending lab results.

**Updated Volume:** None at the time of this update

---

**Date:** 11/13/2020      **Status:** Correspondence - No Action Required

**Author:** Martin, Russell

**Notes:**

Received final report on site. All lab results below NDDEQ action levels except for one small area directly underneath an active crude oil line that was left in place. Excavated areas have been refilled and regraded, will be replanted when field is cultivated next year.

**Updated Volume:** None at the time of this update