# General Environmental Incident Summary

*Incident:* 10627 *Notice:* 12/7/2020 0804 *Occurred:* 12/6/2020 0940

DEM Incident No: No Further Action: 

✓

**Responsible Party:** Marathon Petroleum

County: Dunn

Twp Rng Sec Qtr: 145 95 32

Lat Long + Method: 47.34253 -102.80350 Interpolation from map

Location Description: Marathon Transport Killdeer Facility. 509 109th Ave. SW. Killdeer, ND

Submitted By Info: Jason Tansey

539 S. Main St.

Findlay OH 45840

Received By Info:

Contact Info: Jason Tansey

539 S. Main St.

Findlay OH 45840

Affected Medium: 03 - soil

Near. Occupied Bldg: 180 Feet

Type of Incident: transport hose

Release Contained: Yes

Reported to NRC: Unknown
Contaminant: Crude Oil
Volume of Release: 35 gallons

Duration of Release: 1 minutes

Agriculture Related: No

**EPA Extremely** 

Hazardous Substance: NoNumber of Fatalities: 0Number of Injuries: 0

Cause of Incident:

The Marathon transport driver was attempting to offload a trailer that had malfunctioned when loading at the well pad the previous night when a similar issue occurred.

#### Risk Evaluation:

None

### Potential Env. Impacts:

None

#### Action Taken/Planned:

Oil spray was localized to the immediate area and contacted adjacent transports. Impacted soils were collected for disposal at an approved facility. No one was injured. The transport has been removed from service for evaluation.

## Wastes Disposal Location:

SM Fence was hired to manage soil removal.

## Other Agencies Involved:

**PHMSA** 

## **Updates**

Date: 12/7/2020 Status: Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident the release impacted the surrounding area. Follow-up is necessary to

ensure proper cleanup.

**Updated Volume:** None at the time of this update

Date: 12/7/2020 Status: Correspondence - More Follow-up Required

Author: Stockdill, Scott

Notes:

Email sent to responsible party.

"... Do you have any photos of the incident or the location of the impacted area. ..."

Full email in the incident folder.

More follow-up is necessary.

Updated Volume: None at the time of this update

Date: 12/7/2020 Status: Correspondence - More Follow-up Required

Author: Stockdill, Scott

Notes:

Email from responsible party.

"... Attached are photos from our field operations. ..."

Full email and photos in the incident folder.

Attached photos indicate impacts that flowed out onto an permeable surface.

More follow-up is necessary to ensure proper cleanup.

Updated Volume: None at the time of this update

Date: 12/7/2020 Status: Correspondence - More Follow-up Required

Author: Stockdill, Scott

Notes:

Email sent to responsible party.

"... We will look at getting an inspector out to check it out sometime this week. ..."

Full email in the incident folder.

More follow-up is necessary.

**Updated Volume:** None at the time of this update

Date: 12/22/2020 Status: Inspection - No Action Required

Author: Kaiser, Don

Notes:

Visited site on 12/21/2020. Company representative informed me that soil from impacted area had been removed and replaced with new soil. No sign of residual oil from incident. Photos are in incident report folder. Recommend site be closed.

Updated Volume: None at the time of this update

Date: 1/11/2023 Status: Correspondence - No Action Required

Author: Suess, Bill

Notes:

Bill Suess sent a No Further Action letter dated January 11, 2023.

Updated Volume: None at the time of this update