

General Environmental Incident Summary

Incident: 5406 **Notice:** 5/19/2017 1100 **Occurred:** 5/17/2017 1600

DEM Incident No:

No Further Action:

Responsible Party: Williams County Highways Department

County: Williams

Twp Rng Sec Qtr: 154 101 23 NE

Lat Long + Method: 48.15405 -103.62630 Interpolation from map

Location Description: Former Williams County Highway Department building
213 11 st W
Williston, ND
58801

Submitted By Info: Bryan Koehler
LT Environmental
634 E Broadway
Williston ND 58801

Received By Info:

Contact Info: Tuguldur Shinezorig
5218 141st Ave NW
Williston ND 58801

Affected Medium: 03 - soil

Near. Occupied Bldg: 100 Feet

Type of Incident: Pump Leak

Release Contained: Yes

Reported to NRC: No

Contaminant: Diesel fuel

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Leak of diesel fuel from transfer pump located at top of Underground Storage Tanks (UST). Was noted during tank removal.

Risk Evaluation:

No immediate risk associated with the release

Potential Env. Impacts:

Impacted soil was encountered as a result of the release. No impact to groundwater was noted during excavation activities and no potential impact to surface water was noted.

Action Taken/Planned:

Release noted during scheduled pump/UST removal activities; as such associated infrastructure was removed as part of pre-scheduled activities. Impacted soil totalling approximately 25 yards was excavated and disposed of properly. Confirmation samples were collected by a third party environmental consultant and will be sent in for laboratory testing of TPH-DRO, TPH-GRO, and BTEX.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 5/23/2017 **Status:** Reviewed - Assigned to NDDEQ Division

Author: O'Gorman, Brian

Notes:

According to the report, diesel fuel was released during an underground storage tank (UST) removal. Incident forwarded to Division of Waste Management UST Program for further follow-up.

Updated Volume: None at the time of this update

Date: 5/30/2017 **Status:** Inspection

Author: Schiermeister, Robin

Notes:

Arrived on 5-18-2017 at 14:00. It was sunny and fair. The contamination was right next to the spill bucket and occurred during the removal of two tanks. The hydrocarbon impact measured 23.3 parts per million (below NDDoH standards) on the photo-ionization detector. The responsible party said that the contaminated soil would be removed and the pit backfilled with clean soil. Pictures are in the Closure Inspection Report in the incident folder. Contractors took samples which are in the incident folder. No further follow-up is necessary at this time.

Updated Volume: None at the time of this update

Date: 7/6/2017 **Status:** Correspondence

Author: Schiermeister, Robin

Notes:

Robin Schiermeister sent a No Further Action letter dated July 6, 2017.

Updated Volume: None at the time of this update