General Environmental Incident Summary

| Incident: 5726 | Notice: 5/22/2018 14 | 400 Occurred: 5/22/2018 0200 |
|---------------------------------------|---|--|
| DEM Incident No: | | No Further Action: ✔ |
| Responsible Party: | Minnesota Power | |
| County: | Morton | |
| Twp Rng Sec Qtr: | 140 87 14 | |
| Lat Long + Method: | 46.93868 -101.62680 Inte | erpolation from map |
| Location Description: | Bison wind turbine 3. Take exit 12 then 2.4 miles west on CR140. To is at first turbine (T311). | 20 off I-94, travel north 5 miles on CR86, Furn north on the turbine access road. Spill |
| Submitted By Info: | Ross Dudzik | |
| | 30 West Superior St. | |
| | Duluth MN | |
| Received By Info: | | |
| Contact Info: | | |
| | 30 West Superior St | |
| | Duluth MN | |
| Affected Medium: | 03 - soil | |
| Near. Occupied Bldg: | 4800 Feet | |
| Type of Incident: | Hydraulic cylinder leak | |
| Release Contained: | Yes | |
| Reported to NRC: | Unknown | |
| Contaminant: | Hydraulic oil | |
| Volume of Release: | 30 gallons | |
| Duration of Release: | | |
| Agriculture Related: | No | |
| EPA Extremely Hazardous Substance: | Unknown | |
| Number of Fatalities: | 0 | |
| Number of Injuries: | 0 | |
| Cause of Incident: | | |

Hydraulic cylinder used to control pitch of wind turbine blade failed. Oil leaked to hub of turbine, then to base of turbine.

Risk Evaluation:

Minimal risk, no safety concerns

Potential Env. Impacts:

Gravel/soil at base of tower impacted. No surface water or wetland impacts, groundwater not anticipated to be impacted due to timely cleanup and minimal spill volume.

Action Taken/Planned:

Turbine base, foundation, and transformer will be cleaned. Contaminated rock/soil, absorbent rags, granular absorbents will be collected and disposed

Wastes Disposal Location:

Clean Harbors Sawyer Landfill

Other Agencies Involved:

Updates

Date: 5/22/2018 Status: Reviewed - Follow-up Required

Author: Schiermeister, Robin

Notes:

Release, due to a hydraulic cylinder leak, occurred at a non E&P facility. Further follow-up will be needed with the company to ensure clean up.

Updated Volume: None at the time of this update

Date: 5/23/2018 *Status:* Correspondence

Author: DeVries, Taylor

Notes:

Received before and after photographs of the remediation. The release of hydraulic fluid hit the base of the tower, along with the transformer and a little part of the gravel pad. The hydraulic fluid has been washed off the tower base and transformer. The affected gravel has been removed as well. Photos of this can be found in the report folder.

No further follow-up is needed at this time.

Updated Volume: None at the time of this update