

# Oil Field Environmental Incident Summary

**Incident:** 20170117073124      **Notice:** 1/17/2017    07:31    **Occurred:** 1/16/2017    11:15

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** FERTILE 54-20H

**Field Name:** PARSHALL

**Well File #:** 25903

**Facility ID #:**

**County:** MOUNTRAIL

**Twp Rng Sec Qtr:** 151 90 20 SE SW

**Location Description:**

**Submitted By:** Danielle Dupay

**Received By:**

**Contact Info:**  
Danielle Dupay  
600 17TH ST STE 1000N  
DENVER CO 80202

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	120	Barrels	100	Barrels	120	barrels
<b>Other</b>						

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 3/24/2017

**Written Report Recd:** 12/15/2017

**Risk Evaluation:**

N/A

**Areal Extent:**

N/A

**Potential Env. Impacts:**

N/A

**Action Taken/Planned:**

A hydrovac was called to remove PW, slush and snow. A skidsteer will be used to remove more snow from the area so the hydrovac can continue removing contaminated soils/slush/water. Open top tanks have been put onsite to contain the contaminated material until disposal and until cleanup is complete.

**Wastes Disposal Location:**

TBD

**Other Agencies Involved:**

TAT, MHA

**Updates**

---

**Date:** 1/17/2017      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the report the release was contained. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

**Updated Volumes and Contaminant**    None at the time of this update