Oil Field Environmental Incident Summary

Responsible Party: Bison Midstream, LLC

Well Operator:

Well Name: East Compressor Station

Field Name: Well File #: Facility ID #:

County: MOUNTRAIL
Twp Rng Sec Qtr: 157 90 35

Location Description: The incident occurred at the East Compressor Station in Mountrail County

(SW1/4, SE1/4, S35, T157N, R90W) at coordinates 48.374914, -

102.265327. The facility is located approximately 11 miles northeast of

Stanley, ND.

Submitted By: Andrew Parisi

Received By:

Contact Info: Andrew Parisi

6401 88th Ave. NW

Ross ND 58776

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Pump Leak

Release Contained: Yes - On Facility Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine

Other 3 Barrels 3 barrels 3

Oth Rel. Contaminant: Condensate

Date Inspected:

Clean Up Concluded: 7/28/2017
Written Report Recd: 8/4/2017

Risk Evaluation:

No impact to surface waters or human health.

Areal Extent:

The spill was contained on property owned by Bison Midstream, LLC.

Potential Env. Impacts:

The spilled condensate froze upon contact with the ground. The condensate impacted the facility topsoil and snow around the knockout tank. There was no impact to, or potential to impact, a water of the State.

Action Taken/Planned:

Operations isolated the frozen line and leaking pump seal until repairs could be made. Operations will install a check valve downstream of the pump to prevent back flow from occurring.

Wastes Disposal Location:

Recovered condensate and impacted soil will be hauled to a licensed disposal facility in the area. *Other Agencies Involved:*

Updates

Date: 1/18/2017 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the report the release was contained to the compressor station. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update