

Oil Field Environmental Incident Summary

Incident: 20170316151222 **Notice:** 3/16/2017 15:12 **Occurred:** 3/16/2017 07:00

Responsible Party: Resource Energy
Well Operator: RESOURCE ENERGY CAN-AM LLC
Well Name: BEL AIR-COMET CTB (1H, 2H, 3H)
Field Name: AMBROSE
Well File #:
Facility ID #: 225634-01
County: DIVIDE
Twp Rng Sec Qtr: 163 99 26 NE NW
Location Description:
Submitted By: Kurt Kukowski
Received By:
Contact Info: Kurt Kukowski

2 WEST SECOND STREET
TULSA OK 74103

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Truck Overflow
Release Contained: Yes - On Constructed Well Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	60	Barrels	60	Barrels		
Other						

Oth Rel. Contaminant:
Date Inspected:

Clean Up Concluded:
Written Report Recd:

Risk Evaluation:
Production water on location.

Areal Extent:
Potential Env. Impacts:

Production water on location.
Action Taken/Planned:

Water hauling company immediately terminated driver. Two Vac trucks sucked up production water and surrounding fresh water puddles. Surrounding puddles tested with mud balance and refractometer. Water hauling company will be having a meeting on 3/17/17 with their drivers about staying outside trucks while loading and offloading.

Wastes Disposal Location:
Other Agencies Involved:

Updates

Date: 3/16/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release, due to truck overflow, remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update