

# Oil Field Environmental Incident Summary

**Incident:** 20170526155145      **Notice:** 5/26/2017      15:51      **Occurred:** 5/25/2017      16:00

**Responsible Party:** Polar Midstream, LLC

**Well Operator:**

**Well Name:**

**Field Name:**

**Well File #:**

**Facility ID #:**

**County:** WILLIAMS

**Twp Rng Sec Qtr:** 155 99 13 NE NW

**Location Description:** The spill occurred at a pig launcher on the 8" pipeline right of way that flows toward Epping near the intersection of 123rd Dr. NW and 58th St. NW.  
Latitude: 48.253681  
Longitude: -103.356639

**Submitted By:** Andrew Parisi

**Received By:**

**Contact Info:** Andrew Parisi  
5831 123rd Drive NW  
Epping ND 58843

**Affected Medium:** Topsoil

**General Land Use:** Other - Described Above

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.7	Barrels	0.7	Barrels	8.17	

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 6/7/2017

**Written Report Recd:** 6/16/2017

**Risk Evaluation:**

No impact to surface waters.

**Areal Extent:**

The leaking valve sprayed oil impacting approximately 200 sq ft of soil.

**Potential Env. Impacts:**

The spill impacted approximately 12 cubic feet of soil and gravel immediately surrounding the pig launcher. There is no potential for the spill to impact surface water or groundwater. The impacted soil and gravel will be excavated and removed from the location.

**Action Taken/Planned:**

The pig launcher was isolated, drained, and then the bleeder valve was replaced. The impacted soil will be excavated and removed from the site.

**Wastes Disposal Location:**

The recovered waste and impacted soil will be hauled to a licensed disposal facility in the area.

**Other Agencies Involved:**

**Updates**

---

**Date:** 5/26/2017      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

According to the report, a valve/piping connection leak was not contained. More follow-up needed.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 6/9/2017      **Status:** Inspection      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

5/31/2017 at 1:51, on location. Launcher surrounded by an wheat stubble field (does not appear to have been tilled or planted yet). However, majority of staining is limited to area directly around the launcher, with only light staining visible on some stubble in the field. Some of the staining has been scraped up, but more work needs to be done. More follow-up required when cleanup is complete.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 9/29/2017      **Status:** Inspection      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

9/27/2017 at 12:30, on location. Staining has been scraped up, no further follow-up required at this time.

**Updated Volumes and Contaminant**    None at the time of this update