

Oil Field Environmental Incident Summary

Incident: 20170720152218 **Notice:** 7/20/2017 15:22 **Occurred:** 7/19/2017 13:26

Responsible Party: SCOUT ENERGY MANAGEMENT LLC

Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: RIDL 11-1

Field Name: ELAND

Well File #: 13724

Facility ID #:

County: STARK

Twp Rng Sec Qtr: 139 97 11 SE NW

Location Description:

Submitted By: Beki Sample

Received By:

Contact Info:
Beki Sample
4901 LBJ FREEWAY, STE 300
DALLAS TX 75244

Affected Medium: Topsoil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 2500 Feet

Nearest Water Well: 2500 Feet

Type of Incident: Pipeline Leak

Release Contained: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	20	Gallons	20	Gallons	10	gallons
Brine	20	Gallons	20	Gallons	10	gallons

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 8/21/2017

Written Report Recd: 9/15/2017

Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Env. Impacts:

Approximately a 10' x 7' patch of dry grass has oil/water mix on it which may cause it to die.

Action Taken/Planned:

Line will be dug up on Monday after One-Call comes back and line with leak will be replaced. Contaminated soil will be removed and reseeding if necessary.

Wastes Disposal Location:

R360 Chimney Butte

Other Agencies Involved:

Updates

Date: 7/20/2017 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: Schiermeister, Robin

Notes:

Release, due to a pipeline leak, affected the soil surrounding it. Further follow-up is needed to determine if proper clean up is being conducted.

Updated Volumes and Contaminant None at the time of this update

Date: 8/10/2017 **Status:** Inspection

No Further Action:

Author: O'Gorman, Brian

Notes:

Arrived on location at 15:40. 75 degrees F, Partly Cloudy, East wind 5-10 mph. Observed the site and took photos. Spoke with a contractor on-site who pointed out the area where the release occurred (near a electrical box on east side of the well pad, approximately 30 feet inside the cattle guard). Earthwork had already been completed with new soil in place at the point of the release. It appeared that the release remained within the well pad boundary. No further follow-up needed at this time.

Updated Volumes and Contaminant None at the time of this update