Oil Field Environmental Incident Summary

Incident: 20170916174320 Notice: 9/16/2017 17:43 Occurred: 9/16/2017 08:00

Responsible Party: WPX ENERGY WILLISTON, LLC Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: CARIBOU 33-34HDL

Field Name: MANDAREE

Well File #: 32677

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 150 93 32

Location Description:

Submitted By: Robert Raup

Received By:

Contact Info: Robert Raup

3500 One Williams Center- MD38

TULSA OK 74172

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	45	Barrels	45	Barrels	45	barrels
Brine	45	Barrels	45	Barrels	45	barrels
Other			10	Barrels	10	barrels

Oth Rel. Contaminant: The extra ten barrels accounted for the stormwater that was inside of the

secondary containment from yesterday's rain event.

Date Inspected:

Clean Up Concluded: 9/18/2017 Written Report Recd: 1/31/2018

Risk Evaluation:

There are no immediate risks associated with this incident at this time.

Areal Extent:

The release was entirely contained within the jet pump's lined secondary containment.

Potential Env. Impacts:

There are no potential environmental impacts associated with this incident. The fluids were removed from the lined secondary containment with the use of a vacuum truck. It should be noted that no fluids migrated passed the lined secondary containment.

Action Taken/Planned:

The fluids have been removed with the use of a vacuum truck. A roustabout crew will be on-site Monday to pressure wash the equipment and remove additional oil/salt stains on the equipment and liner. WPX will look to address the vibration issues in hopes of preventing a future occurrence.

Wastes Disposal Location:

Secure Energy's Full Service Terminal - Keene, ND

Other Agencies Involved:

MHA/TAT BIA

Updates

Date: 9/18/2017 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Martin, Russell

Notes:

Release due to valve/piping connection leak, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update