

# *Oil Field Environmental Incident Summary*

**Incident:** 20171111184359      **Notice:** 11/11/2017 18:43      **Occurred:** 11/11/2017 08:30

**Responsible Party:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** STOWERS 5502 43-8H

**Field Name:** SQUIRES

**Well File #:** 18799

**Facility ID #:**

**County:** WILLIAMS

**Twp Rng Sec Qtr:** 155 102 8

**Location Description:**

**Submitted By:** Dustin Anderson

**Received By:**

**Contact Info:**  
Dustin Anderson  
1001 FANNIN STE 1500  
HOUSTON TX 77002

**Affected Medium:** Topsoil

**General Land Use:** Cultivated

**Near. Occupied Bldg:** 1 Mile

**Nearest Water Well:** 1 Mile

**Type of Incident:** Treater Leak

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	8	Barrels	7	Barrels	7	barrels
<b>Brine</b>	2	Barrels	1	Barrels	1	barrels

**Other**

**Oth Rel. Contaminant:** produced water and crude oil

**Date Inspected:**

**Clean Up Concluded:** 12/15/2017

**Written Report Recd:** 1/30/2018

**Risk Evaluation:**

Low - snow buffered most of the mist. Soil will be removed for off-site disposal as soon as the utility locate clears.

**Areal Extent:**

22,850

**Potential Env. Impacts:**

Low - snow buffered most of the mist. Soil will be removed for off-site disposal as soon as the utility locate clears.

**Action Taken/Planned:**

Preventative maintenance

**Wastes Disposal Location:**

Secure 13-mile landfill

**Other Agencies Involved:**

## Updates

---

**Date:** 11/14/2017    **Status:** Reviewed - Follow-up Required

**No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, the release of production water and crude oil was not contained to the well pad perimeter. Further follow-up is needed.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 11/14/2017    **Status:** Inspection

**No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

Arrived on location 11/14/2017. Photos taken and added to incident folder.

Spray from treater to east roughly 200 yards wide by 100 yards in length. No sign of remediation work at this time.

Contact Company regarding cleanup.

More follow-up is necessary.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 12/4/2017    **Status:** Inspection

**No Further Action:**

**Author:** Nieraeth, Shawna

**Notes:**

Arrived on site at 11/28/2017 at the behest of Scott Stockdill, to check if Oasis had begun work. Work had begun. Spoke with Oasis Contractor A. Coyles on site. He said that they were finishing up vacuuming up the fluid that day and would begin excavating the next day. No photos taken.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 12/27/2017    **Status:** Inspection

**No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

Arrived on location 12/27/2017. Photos taken and added to incident folder.

Impacted material has been excavated and backfilled. No sign of remaining contaminants. Revisit in spring/summer to collect confirmation samples and ensure vegetation regrowth.

More follow-up is necessary.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 1/5/2018      **Status:** Inspection

**No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

Inspection Date: 1/5/2018. Arrived on site at 0920. Photos were taken and can be found in the incident folder.

Snow is covering excavated area. Further follow-up in spring and summer to check on vegetation regrowth.

**Updated Volumes and Contaminant**   None at the time of this update

---

**Date:** 4/26/2018      **Status:** Inspection

**No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

Arrived on location 2:50 4/26/2018. Photos taken and added to incident folder.

No sign of remaining contamination or contaminants. Request any final documentation regarding site from responsible party.

Follow-up on site mid-summer to check crops in field.

**Updated Volumes and Contaminant**   None at the time of this update

---

**Date:** 8/2/2018      **Status:** Inspection

**No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

Arrived on location 14:42 8/2/2018.

No sign of remaining contaminants or contamination. Impacted field has healthy crop with sporadic kochia throughout it.

No follow-up is necessary.

**Updated Volumes and Contaminant**   None at the time of this update