

Oil Field Environmental Incident Summary

Incident: 20180102134832 **Notice:** 1/2/2018 13:48 **Occurred:** 1/2/2018 10:30

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: SALO 1-26H

Field Name: HAMLET

Well File #: 17587

Facility ID #:

County: DIVIDE

Twp Rng Sec Qtr: 160 96 26

Location Description:

Submitted By: Ryan Rasmussen

Received By:

Contact Info: Ryan Rasmussen
PO BOX 268870
OKLAHOMA CITY OK 73126

Affected Medium: Topsoil

General Land Use: Cultivated

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Gallons	10	Gallons	0	gallons

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 5/18/2018

Written Report Recd: 5/18/2018

Risk Evaluation:

None

Areal Extent:

30 foot by 20 foot area off location to the East

Potential Env. Impacts:

Topsoil/Well facility site soil

Action Taken/Planned:

Upon landowners request, leaving the misted oil off location to naturally attenuate. Will conduct soil samples of the topsoil in the spring. The contaminated well site top soil will be scraped up.

Wastes Disposal Location:

TBD

Other Agencies Involved:

NDDOH Bill Suess 1:30 pm January 2, 2018, NDIC Jonathan Rumppe 1:40 pm January 2, 2018, Michael Rindel 1:20 pm January 2, 2018

Updates

Date: 1/2/2018 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to equipment failure, was not contained, according to the report. Further follow-up needed.

Updated Volumes and Contaminant None at the time of this update

Date: 1/3/2018 **Status:** Inspection **No Further Action:**

Author: DeVries, Taylor

Notes:

Inspection Date: 1/3/2018

Arrived on location at 1530. A very fine crude oil mist is seen around the flare. It is hard to delineate extent due to drifting snow. Further follow-up in spring to check on vegetation. Photos were taken and can be found in the report folder.

Updated Volumes and Contaminant None at the time of this update

Date: 8/29/2019 **Status:** Awaiting Documentation **No Further Action:**

Author: Suess, Bill

Notes:

The RP has been contacted to request verification of remediation at the site. Once the documents are reviewed the site will be revisited to assure proper revegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 1/3/2020 **Status:** Correspondence - Vegetation Check **No Further Action:**

Author: Suess, Bill

Notes:

Received follow-up report from the RP. Vegetation check needed in Spring 2020.

Updated Volumes and Contaminant None at the time of this update

Date: 8/31/2020 **Status:** Inspection - No Action Required **No Further Action:**

Author: Suess, Bill

Notes:

Inspected the site on 8/28/2020. No adverse environmental impacts associated with this incident were observed. The vegetation appears healthy and consistent with the surrounding area. The site had been recently hayed. No further action is warranted at this time.

Updated Volumes and Contaminant None at the time of this update