

# Oil Field Environmental Incident Summary

**Incident:** 20180104101552      **Notice:** 1/4/2018      10:15      **Occurred:** 1/2/2018      19:00

**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Name:** LOVAAS TRIPAD CTB

**Field Name:** BLUE BUTTES

**Well File #:**

**Facility ID #:** 232902-01

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 150 96 1 LO 1

**Location Description:** An oil to flare occurred causing a mist in an area of 125' by 25' resulting in a 3.71 bbl. Spill occurred on and off location.

**Submitted By:** Josey Adams

**Received By:**

**Contact Info:** Josey Adams  
600 N. DAIRY ASHFORD  
HOUSTON TX 77079

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3.7	Barrels	3.7	Barrels	3.7	barrels

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 1/8/2018

**Written Report Recd:** 1/10/2018

**Risk Evaluation:**

Oil Contamination to the Ground

**Areal Extent:**

125 feet by 25 feet

**Potential Env. Impacts:**

Oil Contamination to the Ground

**Action Taken/Planned:**

Work order submitted to clean up contaminated snow and soil.

**Wastes Disposal Location:**

Tervita Landfill

**Other Agencies Involved:**

## Updates

**Date:** 1/4/2018      **Status:** Reviewed - Follow-up Required

**No Further Action:** ☒

**Author:** O'Gorman, Brian

**Notes:**

Release, due to equipment failure, was not contained, according to the report. Further follow-up needed.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 1/9/2018      **Status:** Inspection

**No Further Action:** ☒

**Author:** Washek, Sandi

**Notes:**

Arrived on-site at 10:16am; weather was partly overcast with wind out of the SW at 5 miles/hour temperature of 25 degrees F.

The area of impact is located to the north of the flare in a grassy hay area. It also appears to be the same area that was impacted from a previous incident dated 11-17-2017. GPS N47.84731 W102.90275. The area is about 25 feet by 125 feet. Visible oil sheen on fence post to the north of the field along the gravel road. Photos taken and added to incident folder.

Additional follow-up will be needed for this site.

**Updated Volumes and Contaminant**

Oil		Salt Water		Other	
3.70	barrels				
Other Contaminant					

---

**Date:** 6/13/2018      **Status:** Inspection

**No Further Action:** ☒

**Author:** Crowdus, Kory

**Notes:**

On location 6/13/2018, at 4:19pm. Vegetation off location is green and growing. Photos taken and added to incident folder.

No further follow-up is required.

**Updated Volumes and Contaminant**    None at the time of this update