

# *Oil Field Environmental Incident Summary*

**Incident:** 20180108080726      **Notice:** 1/8/2018      08:07      **Occurred:** 1/5/2018      09:30

**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Name:** HAYDON 44-22TFH-ULW

**Field Name:** ELIDAH

**Well File #:** 27709

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 151 97 22 SE SE

**Location Description:** Oil had went to flare on the Haydon 44-22TFH-ULW. MSO shut well in. Well was down on a high flowline pressure. 40' by 15' area was affected off of location. Total of .14 bbl. Work order is submitted for cleanup and to have I& E check all tuning forks.

**Submitted By:** Josey Adams

**Received By:**

**Contact Info:** Josey Adams  
600 N. DAIRY ASHFORD  
HOUSTON TX 77079

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 855 Feet

**Nearest Water Well:** 855 Feet

**Type of Incident:** Equipment Failure

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.1	Barrels	0.1	Barrels	0.14	barrels

**Brine**

**Other**

**Oth Rel. Contaminant:** Oil to flare

**Date Inspected:**

**Clean Up Concluded:** 1/8/2018

**Written Report Recd:** 1/10/2018

**Risk Evaluation:**

Oil to the ground

**Areal Extent:**

40 feet by 15 feet

**Potential Env. Impacts:**

Oil to the ground

**Action Taken/Planned:**

Work order is submitted for cleanup and to have I& E check all tuning forks.

**Wastes Disposal Location:**

Tervita Landfill

**Other Agencies Involved:**

**Updates**

---

**Date:** 1/8/2018      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release impacted areas off location. Follow-up is required.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 1/9/2018      **Status:** Inspection      **No Further Action:**

**Author:** Washek, Sandi

**Notes:**

Arrived on-site at 2:23pm; weather was partly sunny with wind out of the SW at 5 miles/hour and temperature of 43 degrees F. The area of impact was located to the west of the flare in a hayfield. GPS N47387751 W103.07243. No surface waters were impacted.

The snow and vegetation was covered with a light mist of oil. The impacted area off site has not been cleaned up yet, but in conversation with a company rep, he informed the NDDoH inspectors that a cleanup order has been issued for the site. The area of impact is about 40 feet wide x 20 feet long. Photos taken and added to incident folder.

Additional follow-up is needed.

**Updated Volumes and Contaminant**

Oil		Salt Water		Other	
0.10	barrels				
Other Contaminant					

---

**Date:** 6/13/2018      **Status:** Inspection      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

On location 6/13/2018, at 3:04pm. Area off location to the west is green and growing with no signs of distress noticed at this time. Photos taken and added to incident folder.

No further follow-up required.

**Updated Volumes and Contaminant**    None at the time of this update