Oil Field Environmental Incident Summary

Incident: 20180115143306 Notice: 1/15/2018 14:33 Occurred: 1/14/2018 09:00

Responsible Party: RESOURCE ENERGY CAN-AM LLC
Well Operator: RESOURCE ENERGY CAN-AM LLC

Well Name: ELLA 4-15-163-102

Field Name: SKJERMO Well File #: 27187

Facility ID #:

County: DIVIDE

Twp Rng Sec Qtr: 163 102 15

Location Description:

Submitted By: Kurt Kukowski

Received By:

Contact Info: Kurt Kukowski

1805 SHEA CENTER DR, STE 100 HIGHLANDS RANCH CO 80129

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - On Facility Site

Reported to NRC: No

SpilledUnitsRecoveredUnitsOil10Barrels10BarrelsBrine20Barrels20Barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd: Risk Evaluation:

Production fluids on location

Areal Extent:

Potential Env. Impacts:

Production fluids on location

Action Taken/Planned:

Pumper immediately isolated valves at wellhead, also did some gravel work to keep from spreading. Vac truck immediately came to suck up pooled fluids. HVAC will come back this Wednesday with the warmer weather and will finish sucking up contaminated gravel. Pumper was talked to about having plugs to cap off ends of plumbing and not just relying on valves.

Wastes Disposal Location:

Other Agencies Involved:

Followup

Units

Updates

Date: 1/16/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Martin, Russell

Notes:

Release, due to valve/piping connection leak, remained on location, according to the report. NDIC

retains oversight.

Updated Volumes and Contaminant None at the time of this update