

# Oil Field Environmental Incident Summary

**Incident:** 20180117152802      **Notice:** 1/17/2018    15:28      **Occurred:** 1/16/2018    15:27

**Responsible Party:** SCOUT ENERGY MANAGEMENT LLC

**Well Operator:** SCOUT ENERGY MANAGEMENT LLC

**Well Name:** SFTU    2-23

**Field Name:** FRYBURG

**Well File #:** 13515

**Facility ID #:**

**County:** BILLINGS

**Twp Rng Sec Qtr:** 139   101   23   NE NW

**Location Description:**

**Submitted By:** Beki Sample

**Received By:**

**Contact Info:** Beki Sample  
4901 LBJ FREEWAY, STE 300  
DALLAS TX 75244

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 1 Mile

**Nearest Water Well:** 1 Mile

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	160	Barrels	160	Barrels		
<b>Other</b>						

**Oth Rel. Contaminant:** N/A

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

N/A

**Areal Extent:**

N/A

**Potential Env. Impacts:**

N/A

**Action Taken/Planned:**

A fresh water truck will be sent to location to thaw the frozen water. A vac truck will also be on site to suck up both the fresh and production water.

**Wastes Disposal Location:**

A selected water disposal facility.

**Other Agencies Involved:**

US Forest Service

## ***Updates***

---

***Date:*** 1/17/2018

***Status:*** Reviewed - Assigned to Other Agency

***No Further Action:*** ☒

***Author:*** Martin, Russell

***Notes:***

Release, due to valve/piping connection leak, remained on location, according to the report. NDIC retains oversight.

***Updated Volumes and Contaminant*** None at the time of this update