

Oil Field Environmental Incident Summary

Incident: 20180117162345 **Notice:** 1/17/2018 16:23 **Occurred:** 1/16/2018 17:00

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: STANGELAND 1-18H

Field Name: CRAZY MAN CREEK

Well File #: 20188

Facility ID #:

County: WILLIAMS

Twp Rng Sec Qtr: 153 99 18

Location Description:

Submitted By: Cooper Fink

Received By:

Contact Info:
Cooper Fink
PO BOX 268870
OKLAHOMA CITY OK 73126

Affected Medium: Topsoil

General Land Use: Cultivated

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	25	Gallons	25	Gallons	22	gallons

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 5/17/2018

Written Report Recd: 5/21/2018

Risk Evaluation:

None

Areal Extent:

5 gallons of the total volume misted off the West side of location (150' x 25')

Potential Env. Impacts:

Topsoil

Action Taken/Planned:

Scrape up affected area on location and spread out on the driving path. Waiting for a call back from the landowner to verify what he would like to do with the volume off location.

Wastes Disposal Location:

N/A

Other Agencies Involved:

NDDoH - Bill Suess - 3:55 P.M. CT 1/17/2018

NDIC - Jessica Gilkey - 4:00 P.M. CT 1/17/2018

Updates

Date: 1/17/2018 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Martin, Russell

Notes:

Release, due to equipment failure, was not contained on location, according to the report. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 1/22/2018 **Status:** Inspection **No Further Action:**

Author: Schmitt, Bryan

Notes:

Date of Inspection: 1/18/2018, Time: 2:00 PM CST, Temp 34F
Spill/Equipment failure occurred on the Southern portion of the pad. The majority of the spill appears to be located on site in a slushy mix. Some impacts to soil and snow were observed off pad to the South. Oil from equipment failure does not seem to have migrated further than pictures show and the impacted area has not yet been addressed by the company. There is a creek to the East of the pad, which did not appear to be impacted from this incident. Pictures were taken and added to the incident folder. Follow-up required.

Updated Volumes and Contaminant None at the time of this update

Date: 8/29/2019 **Status:** Awaiting Documentation **No Further Action:**

Author: Suess, Bill

Notes:

The RP has been contacted to request verification of remediation at the site. Once the documents are reviewed the site will be revisited to assure proper revegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 1/2/2020 **Status:** Correspondence - Vegetation Check **No Further Action:**

Author: Suess, Bill

Notes:

Received follow-up report from the RP. Vegetation check needed in Spring 2020.

Updated Volumes and Contaminant None at the time of this update

Date: 7/23/2020 **Status:** Inspection - No Action Required **No Further Action:**

Author: Suess, Bill

Notes:

Inspected the site on 7/21/2020. No adverse environmental impacts associated with this incident were observed. The vegetation appeared healthy and consistent with the surrounding area. No further action is warranted.

Updated Volumes and Contaminant None at the time of this update