

Oil Field Environmental Incident Summary

Incident: 20180316122340 **Notice:** 3/16/2018 12:23 **Occurred:** 3/15/2018 11:00

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: HILBERT 1

Field Name: CARTER

Well File #: 10383

Facility ID #:

County: BURKE

Twp Rng Sec Qtr: 162 90 13 SE SW

Location Description:

Submitted By: William Jansky

Received By:

Contact Info: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON TX 77060

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	20	Barrels	18	Barrels		

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

Minimal

Areal Extent:

Potential Env. Impacts:

Minimal

Action Taken/Planned:

Well was shut in for repairs. A vacuum truck was called to recover fluid. A hot water flush of the impacted area will be scheduled weather permitting. Bioremediation to follow.

Wastes Disposal Location:

Production tanks

Other Agencies Involved:

Updates

Date: 3/16/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Schiermeister, Robin

Notes:

Release, due to tank overflow, remained on the well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update

Date: 4/19/2018 **Status:** Inspection **No Further Action:**

Author: DeVries, Taylor

Notes:

Inspection Date: 4/19/2018

Received a call saying that the release had made it off pad. Arrived on location at 1540. The well pad was torn up from the work that had been performed on it, so it was difficult to tell where the pad ended. There was one small spot of oil that was off of location. The environmental company placed a boom around it and was in the process of shoveling it up. The landowner was on site when I arrived but left before I could talk to him. The person onsite (who was a consultant) told me they did some scraping of the soil on the west and east side of the road that goes to the pumpjack. There was no sheen on the snow melt and the area did not smell of hydrocarbons. The person onsite said that soil samples had been taken, although he was uncertain if any had been taken off-site. Photos of the inspection can be found in the report folder.

Updated Volumes and Contaminant None at the time of this update