

# *Oil Field Environmental Incident Summary*

**Incident:** 20180510111857      **Notice:** 5/10/2018    11:18    **Occurred:** 5/10/2018    07:45

**Responsible Party:** BTA OIL PRODUCERS, LLC  
**Well Operator:** BTA OIL PRODUCERS, LLC  
**Well Name:** 20003 JV-P MORGAN #1 SWD  
**Field Name:** MORGAN DRAW  
**Well File #:** 14996  
**Facility ID #:**  
**County:** BILLINGS  
**Twp Rng Sec Qtr:** 144 102 32 NW SW  
**Location Description:**  
**Submitted By:** KATY REDDELL  
**Received By:**  
**Contact Info:** KATY REDDELL

104 S PECOS STREET  
MIDLAND TX 79701

**Affected Medium:** Well/Facility Soil  
**General Land Use:** Well/Facility Site  
**Near. Occupied Bldg:** 2 Mile  
**Nearest Water Well:** 2 Mile  
**Type of Incident:** Pipeline Leak  
**Release Contained:** Unknown  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	100	Barrels				

**Other**  
**Oth Rel. Contaminant:**  
**Date Inspected:**  
**Clean Up Concluded:**  
**Written Report Recd:**

**Risk Evaluation:**  
75'X50' 2'WIDE.

**Areal Extent:**  
NONE

**Potential Env. Impacts:**  
CROSSED INTO FOREST SERVICE FOR ABOUT 150'

**Action Taken/Planned:**  
REMEDiate SOIL, REPAIR LINE.

**Wastes Disposal Location:**  
INDIAN HILLS DISPOSAL

**Other Agencies Involved:**

## Updates

---

**Date:** 5/10/2018      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 5/11/2018      **Status:** Inspection      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

Inspection Date: 5/10/2018 and 5/11/2018

Arrived on location at 1000 on 5/11/2018. Met with pipeline inspector from the NDIC and walked the area in search of the release. The representative from BTA arrived about an hour into the visit and led us to the origin of the pipeline release. The release occurred by a culvert (47.253528 - 103.656361) and ran through the culvert and through a small ephemeral stream. The release occurred on private property as well as US Forest Service land. The spill migrated approximately 1150 yards onto USFS land. A water sample was taken at the culvert along with EC readings. The sample was brought to the lab on Friday the 11th and will be tested for nutrients, general chemistry, and trace metals.

Photos were taken and can be found in the report folder.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 5/14/2018      **Status:** Inspection      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

At location 5/14/2018, at 1:50pm. The release area and flow path is difficult to determine. No personnel from company is at the site and no work appears to have been done at this time. Follow-up with the company will need to be done to determine area of release and plans moving forward.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 6/14/2018      **Status:** Inspection      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

On location 6/14//2018, at 12:33pm. Walked the area of potential impact. There was dead vegetation and a lack of growth at the release point, near the culvert. The drainage path flowed towards the North. There were some dead trees along the flow path extending approximately 1/4 mile in length. EC readings in the drainage/flow path ranged from background levels, up to 8.3ms/cm. Further follow-up is required.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 6/25/2018      **Status:** Inspection

**No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

Inspection Date: 6/25/2018

Arrived on location at 1930. There has been no work done at this location. Photos were taken and can be found in the report folder. Further follow-up on the clean up.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 9/7/2018      **Status:** Correspondence

**No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Received sample results and proposed plan for remediation. Document has been added to the report folder.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 9/13/2018      **Status:** Inspection

**No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

On location 9/13/2018, at 11:00am. Met with BTA personnel and the US Forest Service to discuss remediation. Biocal was to be applied to the area on Forest Service property. It will also be applied to the private property with the approval of landowner. Area near the release will be excavated to the pipeline for proper abandonment of the line. No photos taken. Further follow-up is required.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 9/4/2019      **Status:** Correspondence

**No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Cleanup will be decided between landowner and company. The Department believes there are two suitable solutions for cleanup in this area. One is removing contamination and the other is using a biocal solution. No further follow-up is required.

**Updated Volumes and Contaminant**    None at the time of this update