

# Oil Field Environmental Incident Summary

**Incident:** 20180522135503      **Notice:** 5/22/2018      13:55      **Occurred:** 5/22/2018      08:30

**Responsible Party:** CONTINENTAL RESOURCES, INC.  
**Well Operator:** CONTINENTAL RESOURCES, INC.  
**Well Name:** CORSICAN FEDERAL 5-15H  
**Field Name:** SANISH  
**Well File #:** 31878  
**Facility ID #:**  
**County:** MOUNTRAIL  
**Twp Rng Sec Qtr:** 153 93 15  
**Location Description:** Fluid to flare misted NW of the pad  
**Submitted By:** Ryan Rasmussen  
**Received By:**  
**Contact Info:** Ryan Rasmussen  
PO BOX 268870  
OKLAHOMA CITY OK 73126  
**Affected Medium:** Topsoil  
**General Land Use:** Pasture  
**Near. Occupied Bldg:**  
**Nearest Water Well:**  
**Type of Incident:** Equipment Failure  
**Release Contained:** No  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	25	Gallons	25	Gallons	0	gallons
<b>Brine</b>						
<b>Other</b>						

**Oth Rel. Contaminant:** Fluid to flare caused fire beneath the flare roughly 10' x 12' and misted over a 100' by 30' area

**Date Inspected:**  
**Clean Up Concluded:** 7/2/2018  
**Written Report Recd:** 7/9/2018  
**Risk Evaluation:**  
N/A  
**Areal Extent:**  
30' x 100' Area misted with crude oil, 10' x 12' fire below the flare  
**Potential Env. Impacts:**  
Topsoil  
**Action Taken/Planned:**  
Grass will be cut and bagged and gravel on location will be scraped, faulty equipment will be fixed  
**Wastes Disposal Location:**  
R360  
**Other Agencies Involved:**  
Steve Thuner NDIC 12:51  
Bill Sues NDDOH 12:54

Arthur Langved Land owner 1:17 (Did not answer, no voicemail will try again)

### **Updates**

---

**Date:** 5/22/2018      **Status:** Reviewed - Follow-up Required      **No Further Action:** ☒

**Author:** Schiermeister, Robin

**Notes:**

Release, due to equipment failure, did not remain on the well pad. An inspection is needed to determine the extent of damages.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 6/4/2018      **Status:** Inspection      **No Further Action:** ☒

**Author:** Schiermeister, Robin

**Notes:**

Arrived on site at 15:10 on 5-30-2018. It was sunny with temperatures in the 70s. Walked around the perimeter of the site and saw no signs of the release. The site was undergoing some form of reconstruction during the inspection. According to the report, the release went northwest of the flare. There was a dirt pile in this area but no signs of scraping. Further follow-up is needed to locate release.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 8/29/2019      **Status:** Awaiting Documentation      **No Further Action:** ☒

**Author:** Suess, Bill

**Notes:**

The RP has been contacted to request verification of remediation at the site. Once the documents are reviewed the site will be revisited to assure proper revegetation.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 1/3/2020      **Status:** Correspondence - Vegetation Check      **No Further Action:** ☒

**Author:** Suess, Bill

**Notes:**

Received follow-up report from the RP. Vegetation check needed in Spring 2020.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 6/5/2020      **Status:** Inspection - No Action Required      **No Further Action:** ☒

**Author:** Suess, Bill

**Notes:**

Inspected the site on 6/4/2020. The vegetation appears healthy and consistent with the surrounding area. No adverse environmental impacts associated with this incident were observed. No further action is warranted. Photos are in the incident folder.

**Updated Volumes and Contaminant**    None at the time of this update