

Oil Field Environmental Incident Summary

Incident: 20180523094634 **Notice:** 5/23/2018 09:46 **Occurred:** 5/22/2018 15:30

Responsible Party: LIME ROCK RESOURCES III-A, L.P.

Well Operator: LIME ROCK RESOURCES III-A, L.P.

Well Name: MANNING SWD 1

Field Name: MANNING

Well File #: 90221

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 143 95 31

Location Description: On the Manning SWD pad, north of the tank battery at the pipeline riser.

Submitted By: Robyn Espinoza

Received By:

Contact Info: Robyn Espinoza
1111 BAGBY, SUITE 4600
HOUSTON TX 77002

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	60	Barrels	53	Barrels		
Other						

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

Contaminated surface material

Areal Extent:

Potential Env. Impacts:

Contaminated surface material

Action Taken/Planned:

The standing fluid was recovered by Baranko Bros, SM Fencing will remove all other contaminated materials.

Wastes Disposal Location:

Water-Manning SWD
Solids-Chimney Butte

Other Agencies Involved:

Updates

Date: 5/23/2018 ***Status:*** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: Schiermeister, Robin

Notes:

Release, due to equipment failure, remained on the well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update