

# *Oil Field Environmental Incident Summary*

**Incident:** 20180713212315      **Notice:** 7/13/2018    21:23    **Occurred:** 7/13/2018    04:10

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** Cormylo LCS/CDP

**Field Name:** PARSHALL

**Well File #:**

**Facility ID #:**

**County:** MOUNTRAIL

**Twp Rng Sec Qtr:** 154 90 34 SE SE

**Location Description:** The Wayzetta 14-02H is the closest location to the incident since our compressor stations are not an option. The incident occurred on our Cormylo LCS/CDP site. The legal description i gave is for the actual Cormylo site.

**Submitted By:** Hunter Ball

**Received By:**

**Contact Info:** Hunter Ball  
600 17TH ST., STE 1000N  
DENVER CO 80202

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Fire

**Release Contained:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>					5	barrels

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 8/16/2018

**Written Report Recd:** 9/20/2019

**Risk Evaluation:**

The county road near the facility has been closed to public traffic for approximately 1 mile.

**Areal Extent:**

**Potential Env. Impacts:**

None at this time to the ground, obviously there is smoke being emitted from the fire.

**Action Taken/Planned:**

The tanks that are involved in this fire are inside of a metal containment. As an extra precaution, we built an earthen dike to prevent liquids from leaving the location in the event something happened. Compression activities on the site have stopped, and the tanks have been isolated.

**Wastes Disposal Location:**

**Other Agencies Involved:**

Local Fire Department Local Law Enforcement NDDOH as well as the Mountrail County disaster

emergency services.

### Updates

---

**Date:** 7/13/2018      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Fire at compressor station. Follow-up is required.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 7/14/2018      **Status:** Inspection      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

At location 7/13/2018, at 10:56am. Fire on location at the base of a 400 barrel storage tank. It was estimated that 300 barrels remained in the tank. Fire department was unable to extinguish the fire, so the plan was to let it burn out on its own. Further follow-up is required.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 9/6/2019      **Status:** Awaiting Documentation      **No Further Action:**

**Author:** Suess, Bill

**Notes:**

The RP has been contacted to request verification of remediation at the site. Once the documents are reviewed the site will be revisited to assure proper revegetation.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 9/25/2019      **Status:** Inspection - No Action Required      **No Further Action:**

**Author:** Suess, Bill

**Notes:**

Met with the EOG Environment Manager to inspect the site on 9/24/2019. No signs of impacts were observed. The vegetation in the impact area appears healthy and consistent with the surrounding area. No further action is warranted.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 9/25/2019      **Status:** Correspondence - No Action Required      **No Further Action:**

**Author:** Suess, Bill

**Notes:**

Bill Suess sent a No Further Action letter dated September 25, 2019.

**Updated Volumes and Contaminant**    None at the time of this update