Oil Field Environmental Incident Summary

Incident: 20181104133700 Notice: 11/4/2018 13:37 Occurred: 11/4/2018 07:00

Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: HORNED 147-93-18B-19H

Field Name: MOCCASIN CREEK

Well File #: 25142

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 147 94 13

Location Description:

Submitted By: Joey Sheeley

Received By:

Contact Info: Josh Ruffo

US BANK TOWER

950 17TH ST STE 2200 DENVER CO 80202

Affected Medium: Topsoil

General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: No Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnits10Barrels8barrels

Brine Other

Oil

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 11/12/2018 **Written Report Recd:** 11/13/2018

Risk Evaluation:

None.

Areal Extent:

200 feet x 200 feet.

Potential Env. Impacts:

None.

Action Taken/Planned:

A clean-up crew has been dispatched.

Wastes Disposal Location:

Approved facility. Will have this info when the follow-up report is sent.

Other Agencies Involved:

BLM, MH Energy

Updates

Date: 11/5/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the release was not contained to the well pad. Location is within

MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update