

Oil Field Environmental Incident Summary

Incident: 20190105172335 **Notice:** 1/5/2019 17:23 **Occurred:** 1/4/2019 16:14

Responsible Party: SCOUT ENERGY MANAGEMENT LLC
Well Operator: SCOUT ENERGY MANAGEMENT LLC
Well Name: DICKINSON-HEATH-SAND UNIT 17
Field Name: DICKINSON
Well File #: 4345
Facility ID #:
County: STARK
Twp Rng Sec Qtr: 140 96 28 SW NW
Location Description: This is the line for the DHSU 72. spill was on the fence line of the 17
Submitted By: Beki Sample
Received By:
Contact Info: Beki Sample
 4901 LBJ FREEWAY, STE 300
 DALLAS TX 75244
Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg: 100 Feet
Nearest Water Well: 100 Feet
Type of Incident: Pipeline Leak
Release Contained: No
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2	Barrels	2	Barrels		
Other						

Oth Rel. Contaminant:
Date Inspected:
Clean Up Concluded:
Written Report Recd:
Risk Evaluation:

N/A

Areal Extent:
 The spill is approximately 3 feet x 6 feet.

Potential Env. Impacts:
 There may be some grass kill

Action Taken/Planned:
 Well was shut-in. Spill was contained and a vac truck was dispatched to the site to recover the production water. Hole will be patched.

Wastes Disposal Location:
 Water will be taken to disposal site - unsure which one at this time. Contaminated soil will be taken to R360 Chimney Butte facility.

Other Agencies Involved:

Updates

Date: 1/7/2019 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to a pipeline leak, was not contained, according to the report. Further follow-up needed.

Updated Volumes and Contaminant None at the time of this update

Date: 1/15/2019 **Status:** Inspection **No Further Action:**

Author: DeVries, Taylor

Notes:

Inspection date: 1/14/2019

Arrived on location at 1430. This well pad can be found at these GPS coordinates 46.913747° - 102.808292°. It is located in a residential area. The location of the release is along the east side of the fence. There is new dirt along the fence line. The report says the impacts are 3 x 6 feet. The extent of the new soil is larger than 3 x 6 feet. Contact will be made with responsible party on amount of remediation done. Another site visit will be needed in the summer for a vegetation check.

Photos were taken and can be found in the report folder.

Updated Volumes and Contaminant None at the time of this update

Date: 3/16/2020 **Status:** Inspection - Vegetation Check **No Further Action:**

Author: Martin, Russell

Notes:

3/12/2020 at 17:24, on location. Area on east side still shows the new dirt placed last year, but based on last year's photos, vegetation has started regrowing and infilling in the edges, though the part directly along the fenceline is still mostly bare. More follow-up this growing season.

Updated Volumes and Contaminant None at the time of this update

Date: 8/16/2021 **Status:** Inspection - No Action Required **No Further Action:**

Author: Martin, Russell

Notes:

8/12/2021 at 8:56, on location. Bare spot by fence mostly revegetated. No further follow-up needed.

Updated Volumes and Contaminant None at the time of this update