## Oil Field Environmental Incident Summary

Incident: 20190107191057 Notice: 1/7/2019 19:10 Occurred: 1/7/2019 16:00

Responsible Party:PETRO-HUNT, L.L.C.Well Operator:PETRO-HUNT, L.L.C.Well Name:USA 153-95-4A-9-7H

Field Name: CHARLSON

**Well File #:** 32530

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 154 95 33

Location Description:

Submitted By: Derek Enderud

Received By:

Contact Info: Derek Enderud

390 119th Ave SW

Killdeer ND 58640

Affected Medium: Topsoil
General Land Use: Pasture

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Fire
Release Contained: No
Reported to NRC: No

Spilled Units Recovered Units Followup

0
0

**Units** 

0

Oth Rel. Contaminant: Soot

Date Inspected:

Clean Up Concluded: 1/7/2019
Written Report Recd: 3/13/2019

Risk Evaluation:

Smoke and chance of burn

Areal Extent:

15' x 65'

Oil

**Brine** 

Other

Potential Env. Impacts:

Vegetation is dormant, do not foresee any issues.

Action Taken/Planned:

Fire was put out with extinguishers.

Wastes Disposal Location:

N/A

Other Agencies Involved:

Friday, August 5, 2022 Page 1 of 3

## **Updates**

Date: 1/8/2019 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

**Updated Volumes and Contaminant** None at the time of this update

Date: 1/23/2019 Status: Inspection No Further Action: ✓

Author: Washek, Sandi

Notes:

Arrived onsite at 11:26am, weather was overcast with wind out of the west at 15 miles/hr.

temperature of 27 degrees F. GPS N48.11229 W 102.90441

The area of impact is located southeast of the flares. The vegetation on the ground appears burnt, about 25 wide by 60 feet long. Due to the direction of the wind and the flares going, the NDDoH inspector could not approach the burned area.

Additional follow-up will be needed for this site.

Updated Volumes and Contaminant None at the time of this update

Date: 9/24/2019 Status: Inspection - Vegetation Check No Further Action: ✓

Author: Crowdus, Kory

Notes:

On location 9/24/2019, at 11:44am. Vegetation is starting to recover in the area. There are still some bare areas nearest the flare. This may be due to heat from flare. Further follow up is required to check on vegetation.

**Updated Volumes and Contaminant** None at the time of this update

Date: 10/29/2020 Status: Inspection - Vegetation Check No Further Action: ✓

Author: Lund, Dylan

Notes:

Arrived on location at 1140 on 10/29/2020

Vegetation is starting to grow back east of flare but has not fully recovered. Another vegetation check is needed next summer. Photos were taken and can be found in report folder.

**Updated Volumes and Contaminant** None at the time of this update

Friday, August 5, 2022 Page 2 of 3

Date: 5/26/2021 Status: Inspection - Vegetation Check No Further Action: ✓

Author: DeVries, Taylor

Notes:

Inspection Date: 5/26/2021

Arrived on location at 1730. Inspected the area next to the flare and it looks similar to the previous inspections. Another site inspection is recommended.

Photos were taken and can be found in the incident folder.

Updated Volumes and Contaminant None at the time of this update

Date: 11/3/2021 Status: Inspection - Vegetation Check No Further Action: ✓

Author: Suess, Bill

Notes:

This incident has been re-assigned to K. Crowdus.

Updated Volumes and Contaminant None at the time of this update

Date: 7/26/2022 Status: Inspection - No Action Required No Further Action: ✓

Author: Crowdus, Kory

Notes:

On location 7/26/2022, at 11:49am. Vegetation is growing in the impacted area. Some areas are a little sparse but should continue to fill in. No further follow-up needed.

Updated Volumes and Contaminant None at the time of this update

Friday, August 5, 2022 Page 3 of 3