

Oil Field Environmental Incident Summary

Incident: 20190111160803 **Notice:** 1/11/2019 16:08 **Occurred:** 1/11/2019 11:37

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: OPEDAHL 21X-11

Field Name: CAPA

Well File #: 18903

Facility ID #:

County: WILLIAMS

Twp Rng Sec Qtr: 155 95 11

Location Description: 1 bbl oil off pad W/SW 80' x 280'.

Submitted By: Kaylan Dirkx

Received By:

Contact Info: Kaylan Dirkx
110 WEST 7TH STREET
FORT WORTH TX 76102

Affected Medium: Topsoil

General Land Use: Pasture

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Treater Leak

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Barrels			29	barrels
Brine						
Other						

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 1/21/2019

Written Report Recd: 1/25/2019

Risk Evaluation:

Minimal risk- free liquids will be recovered and returned to production tanks. Impacted material will be removed and disposed of properly.

Areal Extent:

W/SW 80' x 280'

Potential Env. Impacts:

Minimal: free liquids will be recovered and returned to production tanks. Impacted material will be removed and disposed of properly.

Action Taken/Planned:

Gasket will be replaced. Free fluids will be recovered and returned to production tanks, impacted material will be collected and disposed at Indian Hills. Landowner was contacted on 1/11/19 and at this time requested no cleanup take place. Landowner will assess later and will notify XTO if work is needed.

Wastes Disposal Location:

Indian Hills

Other Agencies Involved:

NDDEQ-Taylor Souder (msg)

Updates

Date: 1/11/2019 **Status:** Reviewed - Follow-up Required **No Further Action:** ☒

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 1/15/2019 **Status:** Inspection **No Further Action:** ☒

Author: Stockdill, Scott

Notes:

Arrived on location 12:38 1/15/2018.

Spray from treater to south and west. Impacted snow has been scraped up and piled in the flare pit.

More follow-up is necessary to ensure proper cleanup.

Updated Volumes and Contaminant None at the time of this update

Date: 3/9/2020 **Status:** Correspondence - Vegetation Check **No Further Action:** ☒

Author: DeVries, Taylor

Notes:

A summer vegetation check is recommended at this location. Further follow-up in Summer of 2020.

Updated Volumes and Contaminant None at the time of this update

Date: 8/20/2020 **Status:** Inspection - No Action Required **No Further Action:** ☒

Author: DeVries, Taylor

Notes:

Inspection Date: 8/20/2020

Arrived on location at 1540. The S/SW corner of the well pad has vegetation that is green and growing. Did not observe any struggling vegetation. No further follow-up is needed at this time.

Photos were taken and can be found in the report folder.

Updated Volumes and Contaminant None at the time of this update

Date: 9/4/2020 **Status:** Correspondence - No Action Required **No Further Action:** ☒

Author: DeVries, Taylor

Notes:

Taylor DeVries sent a No Further Action letter dated September 4, 2020.

Updated Volumes and Contaminant None at the time of this update