

Oil Field Environmental Incident Summary

Incident: 20190114105822 **Notice:** 1/14/2019 10:58 **Occurred:** 1/13/2019 10:00

Responsible Party: RESOURCE ENERGY CAN-AM LLC

Well Operator: RESOURCE ENERGY CAN-AM LLC

Well Name: RANCHERO 1819-6H

Field Name: AMBROSE

Well File #: 29014

Facility ID #:

County: DIVIDE

Twp Rng Sec Qtr: 163 98 18

Location Description:

Submitted By: Kurt Kukowski

Received By:

Contact Info: Kurt Kukowski
1805 SHEA CENTER DR, STE 100
HIGHLANDS RANCH CO 80129

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Treater Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	40	Barrels	40	Barrels		
Other						

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

Production water and gas leaking from treater

Areal Extent:

Potential Env. Impacts:

Production water and gas leaking from treater

Action Taken/Planned:

Well was shut in, switched into a back-up treater. Standing fluid was sucked up that day with Vac truck. HVAC truck will suck up contaminated soil. New gravel will be brought in to replace old.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 1/14/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to a treater leak, was contained on the well site, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update