

Oil Field Environmental Incident Summary

Incident: 20190314141601 **Notice:** 3/14/2019 14:16 **Occurred:** 3/13/2019 14:00

Responsible Party: PETRO HARVESTER OPERATING COMPANY, LLC

Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC

Well Name: ANDERSON 44-32H

Field Name: CARTER

Well File #: 14875

Facility ID #:

County: BURKE

Twp Rng Sec Qtr: 162 90 32 SE SE

Location Description:

Submitted By: Bill Bender

Received By:

Contact Info: Bill Bender
5851 LEGACY CIRCLE
SUITE 500
PLANO TX 75024

Affected Medium: Topsoil

General Land Use: Cultivated

Near. Occupied Bldg: 10000 Feet

Nearest Water Well: 10000 Feet

Type of Incident: Equipment Failure

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels			0.5	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 4/8/2019

Written Report Recd: 4/9/2019

Risk Evaluation:

No immediate explosive atmosphere or health hazard risk.

Areal Extent:

An approx. 50' x 150' snow-covered area just off location the northeast.

Potential Env. Impacts:

No impact to surface water or ground water.

Action Taken/Planned:

NDIC Field Inspector Jim Potts was notified via telephone. A minor amount of free oil was vacuumed-up adjacent to the flare. The land owner indicated he did not want equipment in the field to remove the snow surface, and potentially damage the crop of winter wheat in that area. The area will be evaluated after snow melt.

Wastes Disposal Location:

At an approved disposal facility.

Other Agencies Involved:

Updates

Date: 3/14/2019 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Martin, Russell

Notes:

Release due to equipment failure, was not contained on location, according to the report. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 4/7/2019 **Status:** Inspection **No Further Action:**

Author: Schmitt, Bryan

Notes:

Inspection Date: 4/2/2019
Time: 15:20 CT
Temp: 35 F

Impacts were observed on vegetation adjacent to the well pad near the flare. A metal bin was on the well pad and had oil impacted soil in it. No sheen or impacts were observed in the farming land further away from the pad. Check vegetation regrowth at a later date.

Updated Volumes and Contaminant None at the time of this update

Date: 4/15/2020 **Status:** Correspondence - More Follow-up Required **No Further Action:**

Author: Kaiser, Don

Notes:

Emailed company for incident status update on 4/15/2020.

Updated Volumes and Contaminant None at the time of this update

Date: 4/21/2020 **Status:** Correspondence - More Follow-up Required **No Further Action:**

Author: Kaiser, Don

Notes:

Talked on phone with rep regarding incidents. Rep stated that he will send updates when available.

Updated Volumes and Contaminant None at the time of this update

Date: 7/22/2020 **Status:** Correspondence - More Follow-up Required **No Further Action:**

Author: Kaiser, Don

Notes:

Received email from company representative on 7/20/2020. NDIC follow-up spill report and photos from company in incident folder.

Updated Volumes and Contaminant None at the time of this update

Date: 11/24/2020 **Status:** Inspection - More Follow-up Required **No Further Action:**

Author: Kaiser, Don

Notes:

Visited site on 11-19-2020. Existing crop appeared healthy and consistent. Photos are in incident report folder. Further follow-up is needed to confirm permanent vegetation re-growth.

Updated Volumes and Contaminant None at the time of this update

Date: 10/6/2021 **Status:** Inspection - No Action Required **No Further Action:**

Author: Kaiser, Don

Notes:

Visited site on 9/23/2021. Took photos. Impacted area has healthy and consistent vegetation with no signs of residue. Recommend site be closed.

Updated Volumes and Contaminant None at the time of this update