Oil Field Environmental Incident Summary

Incident	201005151120	Notio	e: 5/15/2019	11:29	Occurro	d: 5/14/2019	07:	20
Incident: 201905151129 Responsible Party:		RIM OPERATIN		11.23	Occurre	J , J/ 14/2013	07.	50
Well Operator:		RIM OPERATING, INC.						
Well Name:		HUERFANO 11-13H						
Field Name:		LAKESIDE						
Well File #:		17320						
Facility I								
County:		BURKE						
Twp Rng Sec Qtr:		163 89 13						
Location Description:								
Submitted By:		Liz Ortiz						
Received By:								
Contact Info:		Troy Johnson						
		5 INVERNESS DRIVE EAST						
		ENGLEWOOD CO 80112						
Affected Medium:		Well/Facility Soil						
General Land Use:		Well/Facility Site						
Near. Occupied Bldg:		1 Mile						
Nearest Water Well:		1 Mile						
Type of Incident:		Valve/Piping Connection Leak						
Release Contained:		Yes - Within Dike						
Reported to NRC:		No						
	Spilled	Units	Recovered	Units		Followup	Units	
Oil	145	Barrels	140	Barrels				
Brine								
Other								
Oth Rel. Contaminant:								
Date Inspected:								
Clean Up Concluded:								
Written Report Recd:								
Risk Evaluation:								
Areal Extent:								
Potential Env. Impacts:								
none								
Action Taken/Planned:								
well was shut in immediately. repair recycle line, valves fittings, etc location was washed down with fresh water and oil/water was sucked up and placed in tanks/treater on location								

Wastes Disposal Location:

recovered oil/water will be recovered and placed in tank/treater on location

Other Agencies Involved:

Updates

 Date:
 5/15/2019
 Status:
 Reviewed - Assigned to Other Agency
 No Further Action:
 ✓

 Author:
 Stockdill, Scott
 Stockdill, Scott
 Stockdill, Scott
 Stockdill, Scott

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update