

# Oil Field Environmental Incident Summary

**Incident:** 20190522094453      **Notice:** 5/22/2019    09:44    **Occurred:** 5/22/2019    07:00

**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Name:** VEEDER 14-13H

**Field Name:** BLUE BUTTES

**Well File #:** 16357

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 150 96 13

**Location Description:**

**Submitted By:** KELSY Waggaman

**Received By:**

**Contact Info:** Kelsy Waggaman  
925 North Eldridge Pkwy  
HOUSTON TX 77079

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	20	Barrels				

**Other**

**Oth Rel. Contaminant:** N/A

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None

**Areal Extent:**

N/A

**Potential Env. Impacts:**

Produced water released to ground on location.

**Action Taken/Planned:**

Tank has been drained and the swedge was replaced. A notification has been submitted to clean up the spill.

**Wastes Disposal Location:**

TBD

**Other Agencies Involved:**

## **Updates**

---

**Date:** 5/22/2019      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

Release due to valve/piping connection leak remained on location, according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update