Oil Field Environmental Incident Summary

Incident: 20190522104		e: 5/22/2019	10:47	Occurred: 5/21/2019	9 13:30
Responsible Party:	EQUINOR ENE		10.47	Occurred. 5/21/2018	9 13.30
Well Operator:	EQUINOR ENERGY LP				
Well Name:	MASTON 34-27 CTB				
Field Name:	BANKS				
Well File #:	D/ III C				
Facility ID #:	221508-01				
County:	MCKENZIE				
Twp Rng Sec Qtr:		SE SW			
Location Description:					
Submitted By:	Jimmy Dickson				
Received By:					
Contact Info:	Jimmy Dickson				
	6300 BRIDGE POINT PKY, BLDG 2				
	SUITE 100				
	AUSTIN TX 78	730			
Affected Medium:	Topsoil				
General Land Use:	Well/Facility Site				
Near. Occupied Bldg:					
Nearest Water Well:					
Type of Incident:	Fire				
Release Contained:	No				
Reported to NRC:	No				
Spilled	Units	Recovered	Units	Followup	Units
Oil					
Brine					
Other					
Oth Rel. Contaminant:					
Date Inspected:					
Clean Up Concluded:					
Written Report Recd: Risk Evaluation:					
None					
Areal Extent:					
Burned the grass to the north of location and to the west fence line.					
Potential Env. Impacts:					
None					

Action Taken/Planned:

Equinor Rep attached the S/S tubing back to ½" valve, opened the valve to supply air back to sales gas control valve. Crew stomped out fire. Superintendent will have a Safety Stand Down to discuss Pre Job Planning and Inspections.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 5/22/2019 Status: Reviewed - Assigned to Other Agency

No Further Action: 🗸

Author: Martin, Russell

Notes:

Called report contact. Fire started due to sudden increase of gas sent to flare causing some soot buildup on the flare to be removed, which fell on the dry grass. No oil or condensate was found after the fire was put out. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update