

# *Oil Field Environmental Incident Summary*

**Incident:** 20190702154041      **Notice:** 7/2/2019      15:40      **Occurred:** 7/2/2019      11:04

**Responsible Party:** SCOUT ENERGY MANAGEMENT LLC  
**Well Operator:** SCOUT ENERGY MANAGEMENT LLC  
**Well Name:** FRYBURG HEATH-MADISON UNIT    D-808  
**Field Name:** FRYBURG  
**Well File #:** 3522  
**Facility ID #:**

**County:** BILLINGS  
**Twp Rng Sec Qtr:** 139 101 16 NE E2

**Location Description:** Spill occurred right off the northwest corner of the location and traveled approximately 30 feet to the west

**Submitted By:** Beki Sample

**Received By:**

**Contact Info:** Beki Sample  
 4901 LBJ FREEWAY, STE 300  
 DALLAS TX 75244

**Affected Medium:** Topsoil  
**General Land Use:** Pasture  
**Near. Occupied Bldg:** 0.5 Mile  
**Nearest Water Well:** 0.5 Mile  
**Type of Incident:** Pipeline Leak  
**Release Contained:** No  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	1	Barrels	1	Barrels	1	barrels
<b>Other</b>						

**Oth Rel. Contaminant:** N/A

**Date Inspected:**

**Clean Up Concluded:** 7/3/2019

**Written Report Recd:** 10/14/2019

**Risk Evaluation:**

N/A

**Areal Extent:**

approximately 18" x 30'

**Potential Env. Impacts:**

There may be some vegetation kill

**Action Taken/Planned:**

Well was shut in. One-calls were placed. Line will be dug up and repaired/replaced as needed. A vac truck will be dispatched to recover any water and to clear the flowline of any water

**Wastes Disposal Location:**

Water to public disposal and soil to Indian Hills Disposal

**Other Agencies Involved:**

## Updates

---

**Date:** 7/3/2019      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, the release of 1 barrel of brine was not contained. Further follow-up required.

**Updated Volumes and Contaminant**   None at the time of this update

---

**Date:** 7/15/2019      **Status:** Inspection      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

7/11/2019 at 13:24, on location. Disturbed ground on NW part of pad, however there is a tank about 50 feet further to the NW which also has disturbed ground going to it, indicative of a pipeline connecting the two. Unknown which area of disturbed ground is related to the incident at this time. As both areas are very small in size (<10 sq ft), follow-up in fall to confirm remediation.

**Updated Volumes and Contaminant**   None at the time of this update

---

**Date:** 11/20/2020      **Status:** Inspection - No Action Required      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

11/18/2020 at 13:21, on location, which is the same general area affected in later incident, (see incident #20200131153718). Area appears partially revegetated, however area shows evidence of heavy cattle grazing which appears to be hampering proper revegetation. No apparent impacts from the incident remain, no further follow-up required at this time.

**Updated Volumes and Contaminant**   None at the time of this update