

Oil Field Environmental Incident Summary

Incident: 20190719160514 **Notice:** 7/19/2019 16:05 **Occurred:** 7/18/2019 12:20

Responsible Party: MISSOURI BASIN WELL SERVICE, INC.

Well Operator: MISSOURI BASIN WELL SERVICE, INC.

Well Name: BRENNA SWD 1

Field Name: UNION CENTER

Well File #: 90217

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 152 96 13

Location Description:

Submitted By: Nathan Ehlis

Received By:

Contact Info: Nathan Ehlis

PO BOX 458

BELFIELD ND 58622

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Tank Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	74	Barrels	74	Barrels		

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None, the spill was contained within the tank farm.

Areal Extent:

None, the spill was contained within the tank farm.

Potential Env. Impacts:

None, the spill was contained within the tank farm.

Action Taken/Planned:

The leaking tank was isolated, and the volume of the tank was reduced below the level of the tank hatch. This stopped the spill and allowed for repairs to be made to the tank. A vac truck was brought in to suck up any standing water inside the tank farm berm and a hydrovac was used to remove any contaminated material from inside the berm.

Wastes Disposal Location:

All liquids will be put back into the MBI Brenna 1 SWD, all solid will be taken to an approve solids waste disposal.

Other Agencies Involved:

Updates

Date: 7/19/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to a tank leak was contained, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update