

Oil Field Environmental Incident Summary

Incident: 20190812085724 **Notice:** 8/12/2019 08:57 **Occurred:** 8/9/2019 08:00

Responsible Party: EQUINOR ENERGY LP
Well Operator: EQUINOR ENERGY LP
Well Name: REITEN 23-14 1TFH
Field Name: PAINTED WOODS
Well File #: 23632
Facility ID #:
County: WILLIAMS
Twp Rng Sec Qtr: 154 103 26
Location Description:
Submitted By: Jimmy Dickson
Received By:
Contact Info: Jimmy Dickson
6300 BRIDGE POINT PKY, BLDG 2
SUITE 100
AUSTIN TX 78730

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	335	Barrels	335	Barrels		

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None, Contained to location

Areal Extent:

Potential Env. Impacts:

None

Action Taken/Planned:

Operator Shut in units and LOTO, the dump lines and did energy isolation. Called Supervisor, Called SSU and Spill response team,

Wastes Disposal Location:

13 mile Secure land Disposal.

Other Agencies Involved:

Updates

Date: 8/12/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to a valve/piping connection leak was contained on the well site according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update