

# *Oil Field Environmental Incident Summary*

**Incident:** 20190813100627      **Notice:** 8/13/2019    10:06      **Occurred:** 8/12/2019    15:00

**Responsible Party:** LIME ROCK RESOURCES III-A, L.P.

**Well Operator:** LIME ROCK RESOURCES III-A, L.P.

**Well Name:** DIMOND SWD 1

**Field Name:** DIMOND

**Well File #:** 90191

**Facility ID #:**

**County:** BURKE

**Twp Rng Sec Qtr:** 160 91 24 SW SW

**Location Description:**

**Submitted By:** Dusty tescher

**Received By:**

**Contact Info:** Dusty tescher  
3239 Hwy 22  
PO BOX 2000  
Dickinson ND 58601

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 0.5 Mile

**Nearest Water Well:** 0.5 Mile

**Type of Incident:** Equipment Failure

**Release Contained:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	25	Barrels	25	Barrels		
<b>Brine</b>	10	Barrels	10	Barrels		
<b>Other</b>			240	Barrels		

**Oth Rel. Contaminant:** Crude oil and salt water were released. Rain water that was inside of the containment dike was recovered during cleanup as well.

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

NA

**Areal Extent:**

NA

**Potential Env. Impacts:**

Spill was contained inside of a lined containment. No environmental impact.

**Action Taken/Planned:**

Automation equipment is being diagnosed to find the cause of the failure.

**Wastes Disposal Location:**

Dimond SWD.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 8/14/2019      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this release remained on location. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update