

Oil Field Environmental Incident Summary

Incident: 20190813181223 **Notice:** 8/13/2019 18:12 **Occurred:** 8/13/2019 16:01

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: CHSU 21D-35SH 26

Field Name: CEDAR HILLS

Well File #: 15996

Facility ID #:

County: BOWMAN

Twp Rng Sec Qtr: 132 106 35 NE NW

Location Description: Flow line failed allowing fluid to surface 100 yards north of location 21D-35SH26

Submitted By: Steve Hansen

Received By:

Contact Info:
Roy Madsen
5320 LEGACY DR
PLANO TX 75024-3127

Affected Medium: Topsoil

General Land Use: Other - Described Above

Near. Occupied Bldg: 3844 Feet

Nearest Water Well: 3844 Feet

Type of Incident: Pipeline Leak

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels	0.5	Barrels		
Brine	3.5	Barrels	2	Barrels		

Other

Oth Rel. Contaminant: 1/2 bbl of crude oil and 3 1/2 bbl produced water.

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

none

Areal Extent:

fluid migrated 20 yards to the east

Potential Env. Impacts:

none

Action Taken/Planned:

Line will be dug up repaired and tested.

Wastes Disposal Location:

LMS Disposal.

Other Agencies Involved:

Updates

Date: 8/14/2019 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted the surrounding area. More follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 8/14/2019 **Status:** Inspection

No Further Action:

Author: O'Gorman, Brian

Notes:

Arrived on location at 15:06. 81 degrees F, Sunny, Southeast wind 5-10 mph. Observed the site and took photos. The incident was in native grassland approximately 150 yards north of the well pad. An area approximately 120' long by 25' wide had been scraped up and removed with no staining of exposed soils in this area, except for a hole that had an oil product visible to the surface of the soil. More follow-up needed. Photos added to the incident folder.

Updated Volumes and Contaminant None at the time of this update

Date: 8/23/2019 **Status:** Inspection

No Further Action:

Author: Suess, Bill

Notes:

Visited the site on 8/22/2019. The impacted area has been excavated and backfilled. There were no signs of oil staining and EC levels were similar to background readings. More follow-up will be needed to check for re-vegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 12/3/2020 **Status:** Correspondence - Vegetation Check

No Further Action:

Author: Martin, Russell

Notes:

Based on 2020 aerial imagery, impacted area not well vegetated. Vegetation check needed in 2021 growing season to evaluate.

Updated Volumes and Contaminant None at the time of this update