

# Oil Field Environmental Incident Summary

**Incident:** 20190815161142      **Notice:** 8/15/2019    16:11      **Occurred:** 8/14/2019    01:30

**Responsible Party:** Charles Rider

**Well Operator:** XTO ENERGY INC.

**Well Name:** PELTON FEDERAL 11X-35 CTB

**Field Name:** BEAR CREEK

**Well File #:**

**Facility ID #:** 234016-01

**County:** DUNN

**Twp Rng Sec Qtr:** 148 96 35 NW NW

**Location Description:** Driver was on 13th M St NW 1/4 mile south of Pelton Federal pad

**Submitted By:** Diane Hampton

**Received By:**

**Contact Info:**  
Diane Hampton  
110 WEST 7TH STREET  
FORT WORTH TX 76102

**Affected Medium:** Topsoil

**General Land Use:** Other - Described Above

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained:** Unknown

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	2	Barrels	2	Barrels		

**Other**

**Oth Rel. Contaminant:** N/A

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

Less than 2 barrels all contained and clean up with bobcat and dirt hauled to disposal

**Areal Extent:**

N/A

**Potential Env. Impacts:**

none

**Action Taken/Planned:**

spilled cleaned up and dirt hauled to disposal

**Wastes Disposal Location:**

**Other Agencies Involved:**

## Updates

---

**Date:** 8/16/2019      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this release impacted a road that isn't associated with a well pad. Follow-up is necessary.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 8/29/2019      **Status:** Inspection      **No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

Arrived on location at 10:50. 62 degrees F, Partly Cloudy, Northwest wind 20-30 mph. Drove 1/4 mile from the entrance of the well pad along the release road and took photos. There was an area on the north side of the road that had been disturbed mechanically and did not have any vegetative growth. More follow-up needed. Photos added to the incident folder.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 4/8/2020      **Status:** Correspondence - More Follow-up Required      **No Further Action:**

**Author:** Lund, Dylan

**Notes:**

Contacted RP requesting documentation of cleanup efforts and remediation. Awaiting response to decide further actions.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 4/28/2020      **Status:** Correspondence - More Follow-up Required      **No Further Action:**

**Author:** Lund, Dylan

**Notes:**

Contacted RP using an updated email address and phone number. Requested documentation with proof of clean up and remediation.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 4/30/2020      **Status:** Correspondence - More Follow-up Required      **No Further Action:**

**Author:** Lund, Dylan

**Notes:**

Received disposal documentation from XTO Energy although the responsible party was Black Duck Trucking. Inspection required this summer to ensure remediation.

Documentation is in report folder.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 5/14/2020      **Status:** Inspection - Vegetation Check

**No Further Action:**

**Author:** Lund, Dylan

**Notes:**

Arrived onsite at 11:15AM on 5/14/2020.

1/4 mile down road from well pad on north side of road is the impacted area. Vegetation is just starting to grow back and is looking healthy but is still sparse in some areas. Since this area is not completely remediated yet, another vegetation check is required to ensure full regrowth.

Photos taken and can be found in report folder.

**Updated Volumes and Contaminant**   None at the time of this update

---

**Date:** 6/2/2020      **Status:** Correspondence - Vegetation Check

**No Further Action:**

**Author:** Lund, Dylan

**Notes:**

RP contacted me requesting an update on this incident. Although the remediation work is done, a vegetation check is still required since last inspection shows vegetation was sparse and needs more time to grow in order to determine if there are any further impacts.

**Updated Volumes and Contaminant**   None at the time of this update