

# Oil Field Environmental Incident Summary

**Incident:** 20190817132825      **Notice:** 8/17/2019    13:28    **Occurred:** 8/16/2019    02:30

**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Name:** ZACHERY 14-10H

**Field Name:** HAYSTACK BUTTE

**Well File #:** 20077

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 148 98 10

**Location Description:**

**Submitted By:** Kelsy Waggaman

**Received By:**

**Contact Info:**  
Kelsy Waggaman  
925 North Eldridge Pkwy  
HOUSTON TX 77079

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	9.1	Barrels			9.1	barrels
<b>Brine</b>	6.1	Barrels			6.1	barrels

**Other**

**Oth Rel. Contaminant:** N/A

**Date Inspected:**

**Clean Up Concluded:** 8/23/2019

**Written Report Recd:** 2/28/2020

**Risk Evaluation:**

None

**Areal Extent:**

1 gallon of production fluids spilled off of location.

**Potential Env. Impacts:**

Potential impact to facility topsoil.

**Action Taken/Planned:**

Well has been shut in. All standing fluid has been removed from location with Vactruck. Waiting on Emergency OneCall to excavate further.

**Wastes Disposal Location:**

TBD

**Other Agencies Involved:**

## Updates

---

**Date:** 8/19/2019      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, the release was not contained to the well pad. Further follow-up is needed at this time.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 8/28/2019      **Status:** Inspection      **No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

Arrived on location at 9:54. 65 degrees F, Sunny, Southwest wind 0-5 mph. Observed the site and took photos. It appeared that replacement soil had been placed south of the fence, just south of the well in an east-west direction approximately 6' wide by 90' long. It did not appear that any seed and/or erosion control had been completed. Further follow-up needed during next growing season for vegetation check. Photos added to the incident folder.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 5/4/2020      **Status:** Inspection - Vegetation Check      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

On location 5/4/2020, at 12:19pm. Erosion matting is in place in impacted area. Vegetation is starting to return. A follow-up inspection is needed to check on more complete growth.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 8/24/2021      **Status:** Inspection - Vegetation Check      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

Inspection Date: 8/24/2021

Arrived on location at 1520. The area of concern has sparse grass growth. Erosion control is still in place. Further follow-up is needed next year to assess vegetation growth.

Photos were taken and can be found in the incident folder.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 11/3/2021      **Status:** Inspection - Vegetation Check      **No Further Action:**

**Author:** Suess, Bill

**Notes:**

This incident has been re-assigned to K. Crowdus.

**Updated Volumes and Contaminant** None at the time of this update

---

**Date:** 6/7/2022

**Status:** Inspection - No Action Required

**No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

On location 6/7/2022, at 2:54pm. Vegetation is growing in the area. Erosion control is still in place. No further follow-up needed.

**Updated Volumes and Contaminant** None at the time of this update