

Oil Field Environmental Incident Summary

Incident: 20190826171526 **Notice:** 8/26/2019 17:15 **Occurred:** 8/19/2019 08:00

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: C. M. LOOMER 13

Field Name: BLUE BUTTES

Well File #: 8229

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 150 95 5 NW NW

Location Description: 47.844728,102.8744537

Submitted By: Kathleen Kangas

Received By:

Contact Info: Kathleen Kangas
1501 MCKINNEY
HOUSTON TX 77010

Affected Medium: Topsoil

General Land Use: Cultivated

Near. Occupied Bldg: 0.5 Mile

Nearest Water Well: 0.5 Mile

Type of Incident: Other

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other

Oth Rel. Contaminant: Legacy impacts found during asset retirement. Unknown volume. Offsite impacted area is 24,000 sq ft. Site in process of remediation.

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

exposure to contaminated soil

Areal Extent:

24,000 square feet to the south and east of former facility site.

Potential Env. Impacts:

contaminated soil.

Action Taken/Planned:

Remediation is currently underway.

Wastes Disposal Location:

An approved waste disposal facility.

Other Agencies Involved:

Updates

Date: 8/27/2019 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Stockdill, Scott

Notes:

According to the incident summary, a legacy release is contaminating the surrounding area. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 8/27/2019 **Status:** Inspection **No Further Action:**

Author: O'Gorman, Brian

Notes:

Arrived on location at 14:30. 62 degrees F, Cloudy, Northwest wind 20-30 mph. Observed site and took photographs. There was a large excavation in the area of the well pad. It appeared this area extended to the west of the well pad approximately 100 feet. Will need to review work plan assessment report when received. More follow-up needed. Photos added to the incident report.

Updated Volumes and Contaminant None at the time of this update

Date: 12/31/2020 **Status:** Correspondence - More Follow-up Required **No Further Action:**

Author: DeVries, Taylor

Notes:

A site visit is recommended. Further follow-up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 12/16/2021 **Status:** Inspection - More Follow-up Required **No Further Action:**

Author: DeVries, Taylor

Notes:

Inspection Date: 12/16/2021

Arrived on location at 1630. There was a light layer of snow covering the ground during the time of this inspection. The vegetation looked to have grown very well in the summer months. Did not observe any sparse or bare vegetation. Further follow-up is needed with landowner.

Photos were taken and can be found in the incident folder.

Updated Volumes and Contaminant None at the time of this update

Date: 7/28/2022 **Status:** Inspection - No Action Required **No Further Action:**

Author: Suess, Bill

Notes:

Inspected the site on 7/25/2022. The well pad has been reclaimed. The vegetation appears healthy and consistent with the surrounding area. No further action is warranted.

Updated Volumes and Contaminant None at the time of this update