

Oil Field Environmental Incident Summary

Incident: 20190909090702 **Notice:** 9/9/2019 09:07 **Occurred:** 9/8/2019 10:00

Responsible Party: ENERPLUS RESOURCES USA CORPORATION

Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: MUSKRAT 150-94-04B-09H

Field Name: SPOTTED HORN

Well File #: 29528

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 151 94 33

Location Description:

Submitted By: Joey Sheeley

Received By:

Contact Info:
 Josh Ruffo
 US BANK TOWER
 950 17TH ST STE 2200
 DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other	30	Barrels			0	barrels
--------------	----	---------	--	--	---	---------

Oth Rel. Contaminant: Emulsion

Date Inspected:

Clean Up Concluded: 9/8/2019

Written Report Recd: 10/8/2019

Risk Evaluation:

None.

Areal Extent:

None

Potential Env. Impacts:

None.

Action Taken/Planned:

A vac truck was dispatched and 70 barrels of liquid, including rainwater on the pad, was removed and disposed of at the Dailey 1 SWD well (File #90165).

Wastes Disposal Location:

Dailey 1 SWD (File #90165).

Other Agencies Involved:

BLM, MHA Energy, TAT Environmental

Updates

Date: 9/9/2019

Status: Reviewed - Assigned to Other Agency

No Further Action:

Author: Martin, Russell

Notes:

Release due to equipment failure, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update